CROWN TOYOTA

WAVERLEY AUTOMALL
680 - 1717 WAVERLEY STREET
WINNIPEG, MANITOBA R3T 6A9
TEL: (204) 269-9686 (DIRECT)
FAX: (204) 275-4432
TOLL FREE: 1-866-823-3432
EMAIL: service@CrownToyota.ca
WEBSITE: www.CrownToyota.ca

GST #R8987 66 779

TOIS350048

TOIS350048

PRIVACY POLICY

Your privacy is a priority, we pledge continued respect and protection of your personal information. As a TOYOTA owner or lessee, this information is shared between us and Toyota Canada Inc. This allows us to provide ongoing communications that are relevant to you and your vehicle and which enhance your vehicle ownership. All personal information is maintained securely and from time to time may be supplied to third party agencies to ensure that we can serve your needs.

0201ITOIS350048

ALL ITEMS ARE SUBJECT TO G.S.T.

OUT

INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF $ _____ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS, & ACCESSORIES DESCRIBED IN THIS WORK ORDER.

DATE _____ SIGNATURE _____

CUSTOMER NO.	ADVISOR		TAG NO.	INVOICE DATE	INVOICE NO.
10	ALANA HIEBERT	40293	3611	12/18/19	TOIS350048

CROWN TOYOTA
680-1717 WAVERLEY STREET
WINNIPEG, MB R3T 6A9

finmgr1@crowntoyotascion.ca

LABOUR RATE	LICENSE NO.	KILOMETERS	COLOUR	STOCK NO.
139.95	HLB516	78,286	WHITE/	2503611

YEAR/MAKE/MODEL	DELIVERY DATE	DELIVERY KMS.
16/TOYOTA TRUCK/4RUNNER/4DR SUV 4WD	05/26/16	78,286

VEHICLE I.D. NO	SELLING DEALER NO.	IN SERVICE DATE
J T E B U 5 J R 7 G 5 2 7 9 2 3 6	34027	09/02/15

F.T.E. NO	P.O. NO.	R.O. DATE	
		12/17/19	05/26/16

RESIDENCE PHONE	BUSINESS PHONE	COMMENTS	
	204-269-1572	E# GRN285L-GKAGKA	MO: 78286

LABOR & PARTS----------

J# 1 69TOZZ02 GOVERNMENT SAFETY HOURS: 1.50 TECH(S):68812 189.95
CONDITION: PERFORM MANITOBA PROVINCIAL SAFETY $189.95
REPAIR ITEMS MUST BE COMPLETED IN 30 DAYS
(RE-INSPECTION CHARGE OF 19.95 APPLIES)
CAUSE: SAFETY NUMBER 02901563
CORRECTION: COMPLETED MB SAFETY INSPECTION

JOB # 1 TOTAL LABOR & PARTS 189.95

J# 2 69TOZZ01 T.C.U.V. CERTIFIED HOURS: 1.00 TECH(S):68812 125.00
CONDITION: PERFORM TCUV INSPECTION.
COMPLETE FORM.
PROVIDE PAPERWORK TO SERVICE MANAGER
CAUSE: J 79363
CORRECTION: COMPLETED TCUV INSPECTION

JOB # 2 TOTAL LABOR & PARTS 125.00

J# 3+15TOGS6TPG-016 PROP. SHAFT GREASE HOURS: TECH(S):68812 20.04
CONDITION: COMPLETED PROPELLER SHAFT GREASE
CORRECTION: LUBED DRIVE SHAFT

JOB # 3 TOTAL LABOR & PARTS 20.04

J# 4+18TOZZ01 BRAKE FLUID FLUSH HOURS: TECH(S):68812 122.23
CONDITION: POWER VACUUM AND BLEED HYDRAULIC SYSTEM AND REPLACE WITH
GENUINE TOYOTA BRAKE FLUID.INSPECT HYDRAULIC LINES AND
HOSES
..... $109.95
CORRECTION: COMPLETED BRAKE FLUID FLUSH

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	
JOB # 4	1	C0009-00127	DOT 3 BRAKE FLUID	7.16	7.16

JOB # 4 TOTAL PARTS 7.16

JOB # 4 TOTAL LABOR & PARTS 129.39

J# 5+09TOZ QUICK SERVICE HOURS: TECH(S):68812 20.04
CONDITION: REMOVE AND REPLACE THE CABIN FILTER
CORRECTION: REPLACED FILTER

JOB # 5 TOTAL LABOR & PARTS 20.04

J# 6+01TO7F024-EL OIL & FILTER SERVICE HOURS: TECH(S):68812 20.71
CONDITION: REMOVE AND REPLACE ENGINE OIL & FILTER, INSPECT AIR FILTER,
LUBRICATE LOCKS, LATCHES, AND HINGES, CHECK LIGHTS, HORN,
AND WIPERS, CHECK COOLANT, BRAKE, WASHER FLUID LEVELS.
CHECK AND ADJUST TIRE PRESSURES.
4CYL & 6CYL (SYNTHETIC)...$78.98....8CYL (SYNTH).$89.98
CAUSE: QC<2>
CORRECTION: COMPLETED OIL CHANGE

Internet Service Appointment
www.CrownToyota.ca

TDG-CT-SRVINV

ACCOUNTING COPY-I

[CONTINUED ON NEXT PAGE]

10:48am

THANK YOU

We are striving to keep you Completely Satisfied.

You may soon receive a Service Survey.

	Outstanding 9	10
1. Was appointment available when requested?	○	●
2. Time waiting to speak to someone	○	●
3. Vehicle fixed right the first time	○	●
4. Service completed as promised	○	●
5. Service quality	○	●
6. Customer appreciation	○	●

If you cannot answer "Outstanding" (90% - 100%) please contact our Service Manager at (204) 275-4422. Below 90% reflects insufficient customer care in our opinion.

PAYMENT METHOD

MASTERCARD _____
VISA _____
DEBIT CARD _____
CASH _____
AMEX _____

Shop supplies' fees as shown on this invoice include necessary cleaners & degreasers, misc. clips, bolts, fasteners, connectors, lubricants, etc.

WARRANTY

Unless otherwise indicated, TOYOTA parts are warranteed for 24 months or 40,000 kms, whichever comes first.
Labour is covered if the part was installed by a TOYOTA dealer, TOYOTA parts, like batteries, mufflers, shock absorbers and struts, may have different coverage, shown on a label or other document provided to the customer.

CROWN TOYOTA

WAVERLEY AUTOMALL
680 - 1717 WAVERLEY STREET
WINNIPEG, MANITOBA R3T 6A9
TEL: (204) 269-9686 (DIRECT)
FAX: (204) 275-4432
TOLL FREE: 1-866-823-3432
EMAIL: service@CrownToyota.ca
WEBSITE: www.CrownToyota.ca

GST #R8987 66 779

TOIS350048

TOIS350048

PRIVACY POLICY

Your privacy is a priority, we pledge continued respect and protection of your personal information. As a TOYOTA owner or lessee, this information is shared between us and Toyota Canada Inc. This allows us to provide ongoing communications that are relevant to you and your vehicle and which enhance your vehicle ownership. All personal information is maintained securely and from time to time may be supplied to third-party agencies to ensure that we can serve your needs.

0201ITOIS350048

ALL ITEMS ARE SUBJECT TO G.S.T.

OUT

INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF $ _____ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS, & ACCESSORIES DESCRIBED IN THIS WORK ORDER.

DATE _____ SIGNATURE _____

CUSTOMER NO.	ADVISOR	TAG NO.	INVOICE DATE	INVOICE NO.
10	ALANA HIEBERT 40293	3611	12/18/19	TOIS350048

CROWN TOYOTA
680-1717 WAVERLEY STREET
WINNIPEG, MB R3T 6A9

finmgr1@crowntoyotascion.ca

LABOUR RATE	LICENSE NO.	KILOMETERS	COLOUR	STOCK NO.
139.95	HLB516	78,286	WHITE/	2503611

YEAR/MAKE/MODEL	DELIVERY DATE	DELIVERY KMS.
16/TOYOTA TRUCK/4RUNNER/4DR SUV 4WD	05/26/16	78,286

VEHICLE I.D. NO	SELLING DEALER NO.	IN SERVICE DATE
J T E B U 5 J R 7 G 5 2 7 9 2 3 6	34027	09/02/15

F.T.E. NO	P.O. NO.	R.O. DATE	
		12/17/19	05/26/16

RESIDENCE PHONE	BUSINESS PHONE	COMMENTS	
	204-269-1572	E# GRN285L-GKAGKA	MO: 78286

PARTS	QTY	FP	NUMBER	DESCRIPTION	UNIT PRICE	
JOB # 6	1		PKYZZA1-0W20	OIL CHANGE	44.24	44.24
JOB # 6	1		90430-12028	GASKET	****	****
JOB # 6	1		04152-YZZA1	REPLACEABLE ELEME	****	****
JOB # 6	6		C0BBA-0W2SN-0B	0W20 GF5	****	****
				JOB # 6 TOTAL PARTS		44.24
				JOB # 6 TOTAL LABOR & PARTS		64.95

J# 7+09TOZZ17A WIPER BLADES HOURS: 0.10 TECH(S):68812 14.00
CONDITION: REPLACE THE WIPER BLADES
CORRECTION: INSTALLED WIPER BLADES

PARTS	QTY	FP	NUMBER	DESCRIPTION	UNIT PRICE	
JOB # 7	1		85214-42040	RUBBER, WIPER INS	9.95	9.95
JOB # 7	1		C0222-WTR20	BLADE,WIPER	18.50	18.50
JOB # 7	1		C0222-WTR24	BLADE,WIPER	18.50	18.50
				JOB # 7 TOTAL PARTS		46.95
				JOB # 7 TOTAL LABOR & PARTS		60.95

J# 8+15TOZZ-FRDIFF FRONT DIFF FLUID HOURS: TECH(S):68812 107.80
CONDITION: REPLACE FRONT DIFF FLUID WITH APPLICABLE FLUIDS
CORRECTION: REPLACED FLUID

PARTS	QTY	FP	NUMBER	DESCRIPTION	UNIT PRICE	
JOB # 8	2		C0BBA-75W9X-0D	RPL	8.50	17.00
JOB # 8	3		90430-A0003	GASKET	3.60	10.80
				JOB # 8 TOTAL PARTS		27.80
				JOB # 8 TOTAL LABOR & PARTS		135.60

J# 9+15TOZZ-RDF REAR DIFF FLUID HOURS: TECH(S):68812 99.95
CONDITION: REPLACE REAR DIFF FLUID WITH APPLICABLE OIL
CORRECTION: COMPLETED REAR DIFF FLUID CHANGE

PARTS	QTY	FP	NUMBER	DESCRIPTION	UNIT PRICE	
JOB # 9	2		C0BBA-75W9X-0D	RPL	8.50	17.00
JOB # 9	1		90430-24003	GASKET	3.98	3.98
				JOB # 9 TOTAL PARTS		20.98
				JOB # 9 TOTAL LABOR & PARTS		120.93

J#10+13TOZZ-TBI THROTTLE BODY SERVCE HOURS: TECH(S):68812 125.00
CONDITION: REMOVE AND CLEAN THROTTLE BODY AND LINKAGE TO IMPROVE THROTTLE RESPONSE,ROUGH IDLE AND HESITAIONS
THROTTLE BODY SERVICE $109.95
CAUSE: REMOVED MAIN AIR INTAKE TUBE AND SERVICED THROTTLE BODY AS REQUIRED-REASSEMBLED INTAKE AND TEST-OK
CORRECTION: COMPLETED THROTTLE BODY SERVICE

PARTS	QTY	FP	NUMBER	DESCRIPTION	UNIT PRICE	
JOB # 10	1		C0009-00030	AIR INTAKE CLEANE	7.39	7.39
				JOB # 10 TOTAL PARTS		7.39

Internet Service Appointment
www.CrownToyota.ca

THANK YOU

We are striving to keep you Completely Satisfied.

You may soon receive a Service Survey.

	Outstanding 9	10
1. Was appointment available when requested?	○	●
2. Time waiting to speak to someone	○	●
3. Vehicle fixed right the first time	○	●
4. Service completed as promised	○	●
5. Service quality	○	●
6. Customer appreciation	○	●

If you cannot answer "Outstanding" (90% - 100%) please contact our Service Manager at (204) 275-4422. Below 90% reflects insufficient customer care in our opinion.

PAYMENT METHOD

MASTERCARD _____
VISA _____
DEBIT CARD _____
CASH _____
AMEX _____

Shop supplies' fees as shown on this invoice include necessary cleaners & degreasers, misc. clips, bolts, fasteners, connectors, lubricants, etc.

WARRANTY

Unless otherwise indicated, TOYOTA parts are warranteed for 24 months or 40,000 kms, whichever comes first.
Labour is covered if the part was installed by a TOYOTA dealer, TOYOTA parts, like batteries, mufflers, shock absorbers and struts, may have different coverage, shown on a label or other document provided to the customer.

CROWN TOYOTA

WAVERLEY AUTOMALL
680 - 1717 WAVERLEY STREET
WINNIPEG, MANITOBA R3T 6A9
TEL: (204) 269-9686 (DIRECT)
FAX: (204) 275-4432
TOLL FREE: 1-866-823-3432
EMAIL: service@CrownToyota.ca
WEBSITE: www.CrownToyota.ca

GST #R8987 66 779

TOIS350048

PRIVACY POLICY

Your privacy is a priority, we pledge continued respect and protection of your personal information. As a TOYOTA owner or lessee, this information is shared between us and Toyota Canada Inc. This allows us to provide ongoing communications that are relevant to you and your vehicle and which enhance your vehicle ownership. All personal information is maintained securely and from time to time may be supplied to third party agencies to ensure that we can serve your needs.

TOIS350048

0201ITOIS350048

ALL ITEMS ARE SUBJECT TO G.S.T.

OUT

INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF $ _____ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS, & ACCESSORIES DESCRIBED IN THIS WORK ORDER.

DATE _____ SIGNATURE _____

CUSTOMER NO.	ADVISOR		TAG NO.	INVOICE DATE	INVOICE NO.
10	ALANA HIEBERT	40293	3611	12/18/19	TOIS350048

CROWN TOYOTA
680-1717 WAVERLEY STREET
WINNIPEG, MB R3T 6A9

finmgr1@crowntoyotascion.ca

LABOUR RATE	LICENSE NO.	KILOMETERS	COLOUR	STOCK NO.
139.95	HLB516	78,286	WHITE/	2503611

YEAR/MAKE/MODEL	DELIVERY DATE	DELIVERY KMS.
16/TOYOTA TRUCK/4RUNNER/4DR SUV 4WD	05/26/16	78,286

VEHICLE I.D. NO	SELLING DEALER NO.	IN SERVICE DATE
J T E B U 5 J R 7 G 5 2 7 9 2 3 6	34027	09/02/15

F.T.E. NO	P.O. NO.	R.O. DATE	
		12/17/19	05/26/16

RESIDENCE PHONE	BUSINESS PHONE	COMMENTS	
	204-269-1572	E# GRN285L-GKAGKA	MO: 78286

JOB # 10 TOTAL LABOR & PARTS 132.39

J#11+09TOZZ-AF AIR FILTER HOURS: TECH(S):68812 20.04
CONDITION: REPLACE THE ENGINE AIR FILTER
CORRECTION: REPLACED AIR FILTER.

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	
JOB # 11	1	17801-38051	ELEMENT SUB-ASSEM	25.95	25.95
			JOB # 11 TOTAL PARTS		25.95

JOB # 11 TOTAL LABOR & PARTS 45.99

J#12+02TOZ ALIGNMENT HOURS: 1.00 TECH(S):98193 129.95
CONDITION: FOUR WHEEL ALIGNMENT $129.95
CORRECTION: COMPLETED MB SAFETY INSPECTION

JOB # 12 TOTAL LABOR & PARTS 129.95

MISC	CODE	DESCRIPTION	CONTROL NO	
JOB # A	SSI	SHOP SUPPLIES INTERNAL		51.12
			TOTAL - MISC	51.12

COMMENTS
2503611

TOTALS

CONTROL#	ACCOUNT NUMBER	AMOUNT..
2503611	1390	1226.30

TOTAL LABOR....	994.71
TOTAL PARTS....	180.47
TOTAL SUBLET...	0.00
TOTAL G.O.G....	0.00
TOTAL MISC.CHG.	51.12
TOTAL MISC.DISC	0.00
TOTAL TAX.....	0.00
TOTAL INVOICE $	**1226.30**

APPROVED BY SIGNATURE

THANK YOU

We are striving to keep you Completely Satisfied.

You may soon receive a Service Survey.

	Outstanding 9	10
1. Was appointment available when requested?	○	●
2. Time waiting to speak to someone	○	●
3. Vehicle fixed right the first time	○	●
4. Service completed as promised	○	●
5. Service quality	○	●
6. Customer appreciation	○	●

If you cannot answer "Outstanding" (90% - 100%) please contact our Service Manager at (204) 275-4422. Below 90% reflects insufficient customer care in our opinion.

PAYMENT METHOD

MASTERCARD _____
VISA _____
DEBIT CARD _____
CASH _____
AMEX _____

Shop supplies' fees as shown on this invoice include necessary cleaners & degreasers, misc. clips, bolts, fasteners, connectors, lubricants, etc.

WARRANTY

Unless otherwise indicated, TOYOTA parts are warranteed for 24 months or 40,000 kms, whichever comes first.
Labour is covered if the part was installed by a TOYOTA dealer, TOYOTA parts, like batteries, mufflers, shock absorbers and struts, may have different coverage, shown on a label or other document provided to the customer.

Internet Service Appointment
www.CrownToyota.ca

ACCOUNTING COPY-I [END OF INVOICE] 10:48am

TDG-CT-SRVINV

160-POINT TCUV QUALITY ASSURANCE INSPECTION WORKSHEET

1. The certified identification number on the vehicle is the number on this form.
2. Retain one copy in your sales department, one copy in you service department.
3. For all items adjusted, repaired or replaced, a copy of the work order must be attached.

CERTIFIED USED VEHICLES | TOYOTA

CERTIFICATE NO. J 79363

Dealership Name : CROWN Toyota Dealership Code : 34027

Year: 2016 Make : TOYOTA Model : 4Runner Stock Number : 2503611

Colour: WHITE VIN : JTEBU5JR7G5279236

Date : 12-17-A Original In-Service Date : _____ R.O Number 350048 KMS : 78286

A. VEHICLE SERVICING

	MEETS STDS	ADJUST/ REPAIR
01 Run & print Vehicle History Report and attach	✓	
02 Run a Techstream Health Check and attach diagnostic report	✓	
03 Check for and perform outstanding Safety Recall(s)	✓	
04 VINs match on vehicle and paperwork	✓	
05 Service Campaigns performed	✓	
06 Next scheduled maintenance performed (within 3,000kms / 2mths)	✓	

B. ROAD TEST

	MEETS STDS	ADJUST/ REPAIR
ENGINE		
07 Starts (cold/hot)	✓	
08 Idles	✓	
09 Accelerates & cruises smoothly	✓	
10 Engine (cold/hot & high/low speeds)	✓	
11 Engine fan(s) operate properly	✓	
12 Throttle operates properly during cold start	✓	
TRANSMISSION/TRANSAXLE		
13 Auto/manual operation/shifts (cold/hot)	✓	
14 Shift interlock operates	✓	
15 Clutch operates (smoothly and with proper adjustment)	✓	
16 Drive axle/transfer case operation	✓	
STEERING & SUSPENSION		
17 Steers normal (proper response, centering, free play)	✓	
18 Struts, shocks operate	✓	
BRAKES/ABS		
19 Operate (pedal effort/height appropriate, no pulling, pulsating)	✓	
20 ABS operates properly (via Techstream Health Check)	✓	
ACCESSORIES		
21 All gauges, speedometer, tachometer, odometer, etc operate	✓	
22 Cruise Control System operates	✓	

C. UNDERHOOD

	MEETS STDS	ADJUST/ REPAIR
ENGINE CONTROL SYSTEM		
23 Techstream " Healthcheck" performed & printed	✓	
24 No active or stored codes	✓	
25 Emission controls meet provincial requirements	✓	
ENGINE		
26 Fluid leaks	✓	
27 Hose, lines & seals: coolant, fuel, brake, steering, vacuum, A/C (check condition, leaks)	✓	
28 Belts (check wear, cracks, fraying, proper adjustment)	✓	
29 Power steering pump (check for leaks, noise)	✓	
30 Master cylinder and booster (check for leaks)	✓	
31 Engine mounts not broken/separated	✓	
32 Air filter (replace per Maintenance Schedule)	✓	
33 Ignition system works	✓	
34 Starter operates	✓	
35 Underhood area clean, dressed and touched up as required	✓	
36 All underhood labels are present	✓	
37 No evidence of collision repair		
FLUID - Check condition, level; add or change as required		
38 Under-hood fluids clear and uncontaminated	✓	
39 Engine oil & filter (replace per Maintenance Schedule)	✓	
40 Coolant (freeze point)	✓	
41 Automatic transmission/transaxle clutch fluid	✓	
42 Brake fluid	✓	
43 Washer fluid	✓	
44 Power steering fluid	✓	
COOLING SYSTEM		
45 Radiator cap (perform pressure check, inspect for leaks, condition of tubes, fins)	✓	
46 Water pump (free from leaks and unusual noise)	✓	
47 Coolant recovery tank level sensor works	✓	
48 Engine coolant level within specification	✓	
FUEL SYSTEM		
49 Fuel pump operates	✓	
ELECTRICAL SYSTEM		
50 Perform battery check with Midtronics Gr8	✓	
51 Battery properly sized and secure	✓	
52 Charging system operating properly and within specification	✓	
53 Battery type, condition, fluid level, load test correct	✓	
54 Battery cables and mounts acceptable / check terminals and clean	✓	
55 Alternator output correct (check voltage)	✓	
56 Reset CBES (Customized Body Electronic System)	✓	

D. UNDERBODY

	MEETS STDS	ADJUST/ REPAIR
FRAME		
57 No visible damage, signs of previous repairs, no visible abnormal tire wear	✓	
58 Fuel lines, fuel tank, hoses and couplings not leaking	✓	
EXHAUST SYSTEMS		
59 Entire exhaust system not damaged or leaking / check exhaust hangers	✓	
TRANSMISSION, TRANSAXLE, DIFFERENTIAL, TRANSFER CASE		
60 Drive/axle shafts operate properly with no damage	✓	
61 Inspect transmission/transaxle, transfer case and pan for leaks	✓	
62 Differential fluid level correct with no leaks fill/change as required	✓	
63 Universal joints, CV joints, boots and mounts not damaged, leaking, or excess wear/looseness	✓	
TIRES AND WHEELS		
64 All tires & wheels match, correct size	✓	
65 All tires' tread depth, at least 40% remaining and in good condition. Show tire tread depth FR 10 FL 10 RR 10 RL 10 Spare 10	✓	
66 Normal tire wear, no alignment or sidewall problems	✓	
67 Tire pressures are correct	✓	
68 Wheels cleaned, dressed, free from damage and run-out normal	✓	
69 Wheel covers secure and reasonably free of damage	✓	
SUSPENSION/STEERING		
70 Chassis lubricated (per Maintenance Schedule)	✓	
71 Rack & pinion, linkage, boots not visibly damaged, leaking	✓	
72 Control arms, ball joints, bushings not worn	✓	
73 Sway bars, links, bushings operate correctly	✓	
74 Springs have proper ride height (not sagged)	✓	
75 Struts, shocks not leaking	✓	
76 Wheel alignment correct	✓	
77 No suspension modifications	✓	
BRAKES		
78 Calipers, cylinders operate with no leaks	✓	
79 Pads, shoes, at least 40% of original thickness remaining Show brake pad life Front 85% Rear 75%	✓	
80 Rotors, drums at least 50% of original thickness spec; not scored; run out within factory specs	✓	
81 Brake lines, hoses, fittings not worn or leaking	✓	
82 Parking brake operates/adjusted	✓	

E. VEHICLE EXTERIOR

	MEETS STDS	ADJUST/ REPAIR
ENGINE COMPARTMENT		
83 Compartment is clean	☑	☐
84 Under-hood heat insulator pad is clean	☑	☐
85 Engine and compartment are properly dressed	☑	☐
BODY PANELS & BUMPERS		
86 Body and bumpers free from damage, rust and misalignment	☑	☐
87 Chips and scratches repaired and clear-coated	☑	☐
88 Exterior is washed, clean and free of water spots	☑	☐
89 Wheel wells are clean	☑	☐
90 Paint is free of wax residue	☑	☐
DOORS, HOOD, DECK LID, TAILGATE		
91 Not visibly damaged; paint not mismatched or poor quality	☑	☐
92 Hood release, prop rod/gas struts operate	☑	☐
93 All emblems are present and fully attached	☑	☐
GRILL, TRIM & ROOF RACK		
94 Components free from visible damage and attached	☑	☐
GLASS, OUTSIDE MIRRORS, WIPERS		
95 Windshield free from cracks and stars	☑	☐
96 Side/rear windows free from cracks and stars	☑	☐
97 Mirrors not cracked, visibly damaged	☑	☐
98 Replace wiper blades	☑	☐
EXTERIOR LIGHTS - Operate properly, lenses not damaged		
99 Headlights aligned, auto on/off	☑	☐
100 Fog, driving lights, daytime running lights	☑	☐
101 Brake lights, high-mount brake light	☑	☐
102 Turn signals, side marker lights	☑	☐
103 Parking lights	☑	☐
104 Reverse lights	☑	☐
105 Emergency lights	☑	☐
106 License plate lights	☑	☐

F. VEHICLE INTERIOR

	MEETS STDS	ADJUST/ REPAIR
AIR BAGS & SAFETY BELTS		
107 Air bags intact, no codes, dash light works	☑	☐
108 Safety belts operate, free from cuts or wear	☑	☐
HEAT/VENT/AC/DEFROST - Operate properly		
109 Air conditioning and heating systems	☑	☐
110 Defog/defrost (front, rear, outside mirrors if app.)	☑	☐
111 Cabin air filter (if equipped). Replace if necessary	☑	☐
AUDIO, ALARM & NAVIGATION SYSTEMS - Operate properly		
112 Radio, cassette, CD, DVD, remote, speakers, antenna	☑	☐
113 Vehicle security system	☑	☐
114 Navigation system / Bluetooth system operate and cleared	☑	☐
INTERIOR AMENITIES - Operate properly, no damage		
115 Dash/console	☑	☐
116 Tilt/telescopic steering wheel, column lock	☑	☐
117 Steering wheel operates and off-centre	☑	☐
118 Horn	☑	☐
119 Wipers & washers operate in all modes	☑	☐
120 Lights - instrument panel, courtesy, dome (fade-away), map, foot	☑	☐
121 Remote mirror controls operates properly	☑	☐
122 Ashtrays, lighter, power outlet(s)	☑	☐
123 Glove box, glove box light	☑	☐
124 Sun visors, vanity mirrors & lights	☑	☐
125 Cup holders	☑	☐
126 12v ACC power outlet operates properly	☑	☐
127 Interior remote luggage compartment release operates properly	☑	☐
128 Fuel door release operates properly	☑	☐
129 Master key is present	☑	☐
130 No evidence of previous improper interior repairs	☑	☐
CARPET, TRIM, MATS - Clean, no stains or damage		
131 Carpet (check for rust under it due to flood damage) Single layer of mats secured in hooks. Place extras in trunk	☑	☐
132 Floor mats (if any)	☑	☐
133 Door trim, panels attached	☑	☐
134 Fold-down latches work	☑	☐
135 Headliner	☑	☐
136 Interior is free of debris	☑	☐
137 Free of odor, including heavy fragrance	☑	☐
SEATS		
138 Seats clean, not stained, worn, cut, cracked	☑	☐
139 All seat components and functions operate properly	☑	☐
140 Integrated child safety seats operate	☑	☐
141 Heated and/or cooled seats operate	☑	☐
MOONROOF, CONVERTIBLE TOP		
142 Moonroof operates in all modes	☐	☐
143 Convertible top & cover operate; not damaged	☐	☐

	MEETS STDS	ADJUST/ REPAIR
WINDOWS, DOOR LOCKS - Operate as designed		
144 Door jambs are clean	☑	☐
145 Glass is clean and free of streaks	☑	☐
146 Window tinting clear and conforms to local requirements	☑	☐
147 All keys present and function	☑	☐
148 Door locks & handles (manual & power modes)	☑	☐
149 Window controls (manual & power modes)	☑	☐
150 Remote decklid & fuel door releases	☑	☐
151 All crevices are clean	☑	☐
LUGGAGE COMPARTMENT		
152 Carpet, trim, cargo net; clean, not damaged	☑	☐
153 Luggage compartment light works	☑	☐
154 Jack and tools are correct, present and secured	☑	☐
155 Weather stripping intact, not leaking	☑	☐
156 Spare tire correct size/type, at least 40% tread remaining, no sidewall damage, air pressure correct	☑	☐
157 Spare tire and storage areas are clean	☑	☐
158 Spare tire is securely fastened	☑	☐
159 Trunk latch operates	☑	☐

G. RECONDITIONING & DETAILING

	MEETS STDS	ADJUST/ REPAIR
160 Vehicle has been completely reconditioned/detailed	☑	☐

H. HYBRID TCUV COMPONENTS

To be completed by a Certified Hybrid Technician
Use the intelligent Tester for items 1 - 16

	MEETS STDS	ADJUST/ REPAIR
1 Multi-Information Display	☐	☐
2 Inverter Coolant Level	☐	☐
3 Engine and ECT (Electronically Controlled Transmission)	☐	☐
4 THS (Toyota Hybrid System) related ECU (Hybrid Vehicle Electronic Control Unit)	☐	☐
5 Hybrid HV (High Voltage) Battery	☐	☐
6 Perform "Onboard Equalizing Charge" of HV Battery (if app.)	☐	☐
7 Check Transaxle "Park" function	☐	☐
8 Hybrid power management control module	☐	☐
9 Electric motor/ generator operates properly	☐	☐
10 Power inverter operates properly	☐	☐
11 EV/Eco/Power modes operate properly	☐	☐
12 Multi-information display operates properly	☐	☐
13 Touch Tracer display operates properly	☐	☐
14 Hill Start Assist Control operates properly	☐	☐
15 Remote air conditioning system (if equipped) operates properly	☐	☐
16 Solar powered ventilation system (if equipped) operates properly	☐	☐

I. ADDITIONAL INSPECTION ITEMS WHERE APPLICABLE

	MEETS STDS	ADJUST/ REPAIR
1 Transfers case smoothly switches from 2WD to 4WD and back from 4WD to 2WD	☐	☐
2 Truck bed is in good condition	☐	☐
3 Truck bed-liner is in good condition and secured	☐	☐
4 Tailgate functions properly	☑	☐
5 Rear bumper is in good condition and secured	☑	☐
6 Radio security codes cleared	☑	☐
7 Backup camera operates properly	☑	☐
8 Bluetooth searches for signal	☑	☐
9 SOS (Safety Connect) light illuminates green	☑	☐
10 Lane Keep Assist operates properly	☑	☐
11 Dynamic Radar Cruise Control/Pre-Collision Systems operate properly	☑	☐
12 Intelligent Parking Assist operates properly	☑	☐
13 Owner/Warranty/Maintenance Manuals in glove box	☑	☐
14 Acceptable aftermarket items checked	☑	☐
15 Removal of unacceptable aftermarket items	☑	☐

Required Technician Signature
I certify that all mechanical items have been inspected.

Toyota Trained Technician — Date: 12-17-19

Required Manager Signatures
I certify that all mechanical, detailing and appearance repair standards have been met.

Service Manager — Date: Dec 17/19

Vehicle Sales Manager — Date

Work Order: R000001
VIN: JTEBU5JR7G5279236
Date 12/17/19 4:08 PM

JTEBU5JR7G5279236

Toyota 2016-19 4Runner 4X4 Limited





- One or more values are not within specification. Tire wear, handling and safety problems may result.