CROWN TOYOTA

WAVERLEY AUTOMALL
680 - 1717 WAVERLEY STREET
WINNIPEG, MANITOBA R3T 6A9
TEL: (204) 269-9686 (DIRECT)
FAX: (204) 275-4432
TOLL FREE: 1-866-823-3432
EMAIL: service@CrownToyota.ca
WEBSITE: www.CrownToyota.ca

GST #R8987 66 779

TOIS353960

PRIVACY POLICY

Your privacy is a priority, we pledge continued respect and protection of your personal information. As a TOYOTA owner or lessee, this information is shared between us and Toyota Canada Inc. This allows us to provide ongoing communications that are relevant to you and your vehicle and which enhance your vehicle ownership. All personal information is maintained securely and from time to time may be supplied to third party agencies to ensure that we can serve your needs.

TOIS353960

0201ITOIS353960

ALL ITEMS ARE SUBJECT TO G.S.T.

OUT

INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF $_____ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS, & ACCESSORIES DESCRIBED IN THIS WORK ORDER.

DATE _____ SIGNATURE _____

CUSTOMER NO.	ADVISOR	TAG NO.	INVOICE DATE	INVOICE NO.
10	SHARLIE BOYER 85631	4403	03/19/20	TOIS353960
CROWN TOYOTA 680-1717 WAVERLEY STREET WINNIPEG, MB R3T 6A9	LABOUR RATE: 139.95 / LICENSE NO.: HEA749 / KILOMETERS: 27,774		COLOUR: SILVER/	STOCK NO.: 94403
	YEAR/MAKE/MODEL: 15/TOYOTA/COROLLA/4DR SDN CVT LE		DELIVERY DATE	DELIVERY KMS: 27,500
	VEHICLE I.D. NO: 2 T 1 B U R H E 2 F C 2 7 8 1 6 9		SELLING DEALER NO.: 34027	IN SERVICE DATE
finmgr1@crowntoyotascion.ca	F.T.E. NO	P.O. NO.	R.O. DATE: 03/18/20	
RESIDENCE PHONE	BUSINESS PHONE: 204-269-1572	COMMENTS: MO: 27784		

LABOR & PARTS----------

J# 1 20TOZZR98-CAM AIRBAG CONTROL MODUL HOURS: TECH(S):12282 0.00

CONDITION: COMPLETE OUTSTANDING RECALL R98 - AIRBAG CONTROL MODULE
CAUSE: NOT COMPLETED AT THIS TIME
CORRECTION: NO PART AVAILABLE

JOB # 1 TOTAL LABOR & PARTS 0.00

J# 2 69TOZZ02 GOVERNMENT SAFETY HOURS: 1.50 TECH(S):12282 189.95

CONDITION: PERFORM MANITOBA PROVINCIAL SAFETY $189.95
REPAIR ITEMS MUST BE COMPLETED IN 30 DAYS
(RE-INSPECTION CHARGE OF 19.95 APPLIES)
CAUSE: SAFETY NUMBER 02902404
CORRECTION: PERFORMED MB SAFETY INSPECTION

JOB # 2 TOTAL LABOR & PARTS 189.95

J# 3 69TOZZ01 T.C.U.V. CERTIFIED HOURS: 1.00 TECH(S):12282 125.00

CONDITION: PERFORM TCUV INSPECTION.
COMPLETE FORM.
PROVIDE PAPERWORK TO SERVICE MANAGER
CORRECTION: COMPLETE TCUV INSPECTION

JOB # 3 TOTAL LABOR & PARTS 125.00

J# 4 01TOZ OIL CHANGE HOURS: TECH(S):12282 20.71

CONDITION: REMOVE AND REPLACE ENGINE OIL & FILTER, INSPECT AIR FILTER, LUBRICATE LOCKS, LATCHES, AND HINGES, CHECK LIGHTS, HORN, AND WIPERS, CHECK COOLANT, BRAKE, WASHER FLUID LEVELS.
CHECK AND ADJUST TIRE PRESSURES.
4CYL & 6CYL (SYNTHETIC)...$78.98....8CYL (SYNTH).$89.98
CORRECTION: COMPLETED OIL AND FILTER SERVICE

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	
JOB # 4	1	PKYZZA6-0W20	OIL CHANGE KIT	33.24	33.24
JOB # 4	1	90430-12028	GASKET	****	****
JOB # 4	1	04152-YZZA6	REPLACEABLE ELEME	****	****
JOB # 4	5	C0BBA-0W2SN-0B	0W20 GF5	****	****

JOB # 4 TOTAL PARTS 33.24

JOB # 4 TOTAL LABOR & PARTS 53.95

J# 5 20TOZA ELECTRICAL MISC. HOURS: 0.00 TECH(S):12282 0.00

CONDITION: REMOVE AND REPALCE THE REMOTE START BATTERY
CORRECTION: REPLACED BATTERIES

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	
JOB # 5	2	C0EPP-2025C-05	BATTERY,TRANSMITT	4.15	8.30

JOB # 5 TOTAL PARTS 8.30

JOB # 5 TOTAL LABOR & PARTS 8.30

J# 6 09TOZ QUICK SERVICE HOURS: TECH(S):12282 0.00

CONDITION: PLEASE CONFIRM AN RECORD KMS
CORRECTION: 27774 KMS

Internet Service Appointment
www.CrownToyota.ca

THANK YOU

We are striving to keep you Completely Satisfied.

You may soon receive a Service Survey.

	Outstanding 9	10
1. Was appointment available when requested?	○	●
2. Time waiting to speak to someone	○	●
3. Vehicle fixed right the first time	○	●
4. Service completed as promised	○	●
5. Service quality	○	●
6. Customer appreciation	○	●

If you cannot answer "Outstanding" (90% - 100%) please contact our Service Manager at (204) 275-4422. Below 90% reflects insufficient customer care in our opinion.

PAYMENT METHOD

MASTERCARD _____
VISA _____
DEBIT CARD _____
CASH _____
AMEX _____

Shop supplies' fees as shown on this invoice include necessary cleaners & degreasers, misc. clips, bolts, fasteners, connectors, lubricants, etc.

WARRANTY

Unless otherwise indicated, TOYOTA parts are warranteed for 24 months or 40,000 kms, whichever comes first.
Labour is covered if the part was installed by a TOYOTA dealer, TOYOTA parts, like batteries, mufflers, shock absorbers and struts, may have different coverage, shown on a label or other document provided to the customer.

CROWN TOYOTA

WAVERLEY AUTOMALL
680 - 1717 WAVERLEY STREET
WINNIPEG, MANITOBA R3T 6A9
TEL: (204) 269-9686 (DIRECT)
FAX: (204) 275-4432
TOLL FREE: 1-866-823-3432
EMAIL: service@CrownToyota.ca
WEBSITE: www.CrownToyota.ca

GST #R8987 66 779

TOIS353960

PRIVACY POLICY

Your privacy is a priority, we pledge continued respect and protection of your personal information. As a TOYOTA owner or lessee, this information is shared between us and Toyota Canada Inc. This allows us to provide ongoing communications that are relevant to you and your vehicle and which enhance your vehicle ownership. All personal information is maintained securely and from time to time may be supplied to third party agencies to ensure that we can serve your needs.

TOIS353960

0201ITOIS353960

ALL ITEMS ARE SUBJECT TO G.S.T.

OUT

INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF $ _____ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS, & ACCESSORIES DESCRIBED IN THIS WORK ORDER.

DATE _____ SIGNATURE _____

CUSTOMER NO.	ADVISOR	TAG NO.	INVOICE DATE	INVOICE NO.
10	SHARLIE BOYER 85631	4403	03/19/20	TOIS353960

CROWN TOYOTA
680-1717 WAVERLEY STREET
WINNIPEG, MB R3T 6A9

finmgr1@crowntoyotascion.ca

LABOUR RATE	LICENSE NO.	KILOMETERS	COLOUR	STOCK NO.
139.95	HEA749	27,774	SILVER/	94403

YEAR/MAKE/MODEL	DELIVERY DATE	DELIVERY KMS.
15/TOYOTA/COROLLA/4DR SDN CVT LE		27,500

VEHICLE I.D. NO	SELLING DEALER NO.	IN SERVICE DATE
2 T 1 B U R H E 2 F C 2 7 8 1 6 9	34027	

F.T.E. NO	P.O. NO.	P.O. DATE
		03/18/20

RESIDENCE PHONE	BUSINESS PHONE	COMMENTS
	204-269-1572	MO: 27784

JOB # 6 TOTAL LABOR & PARTS 0.00

J# 7+09TOZZ17A WIPER BLADES HOURS: TECH(S):12282 0.00

CONDITION: INSTALL WIPER BLADES
CORRECTION: INSTALLED WIPER BLADES

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	
JOB # 7	1	C0222-WTR16	BLADE,WIPER	18.50	18.50
JOB # 7	1	C0222-WTR26	BLADE,WIPER	18.50	18.50

JOB # 7 TOTAL PARTS 37.00

JOB # 7 TOTAL LABOR & PARTS 37.00

J# 8+09TOFC4CCF-016 CABIN AIR FILTER HOURS: 0.20 TECH(S):12282 20.04

CONDITION: REMOVE AND REPALCE THE CABIN AIR FILTER $52.99
CAUSE: FILTER DIRTY
CORRECTION: REPLACED THE CABIN FILTER

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	
JOB # 8	1	87139-YZZ20	ELEMENT, AIR REFI	32.95	32.95

JOB # 8 TOTAL PARTS 32.95

JOB # 8 TOTAL LABOR & PARTS 52.99

J# 9+09TOZZ-AF AIR FILTER HOURS: TECH(S):12282 20.04

CONDITION: REPLACE THE ENGINE AIR FILTER
CAUSE: FILTER DIRTY
CORRECTION: REPLACED AIR FILTER.

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	
JOB # 9	1	17801-YZZ05	ELEMENT SUB-ASSEM	19.95	19.95

JOB # 9 TOTAL PARTS 19.95

JOB # 9 TOTAL LABOR & PARTS 39.99

J#10+02TOZ ALIGNMENT HOURS: 1.00 TECH(S):98193 129.95

CONDITION: FOUR WHEEL ALIGNMENT $129.95
CORRECTION: PERFORMED 4 WHEEL ALIGNMENT

JOB # 10 TOTAL LABOR & PARTS 129.95

J#11+11TOZZ21 OIL PRESSURE SWITCH HOURS: 0.60 TECH(S):12282 83.97

CONDITION: UPON COMPLTIGN THE SAFETY INSPECTION IT WAS NOTED THAT THE OIL PRESSURE SWITCH WAS LEAKING
CAUSE: SWITCH LEAKING
CORRECTION: REPLACED LEAKING OIL PRESSURE SWITCH INSTALLED WITH TEFLON TAPE

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	
JOB # 11	1	83530-0E010	SWITCH ASSEMBLY,	82.00	82.00

JOB # 11 TOTAL PARTS 82.00

JOB # 11 TOTAL LABOR & PARTS 165.97

Internet Service Appointment
www.CrownToyota.ca

THANK YOU

We are striving to keep you Completely Satisfied.

You may soon receive a Service Survey.

	Outstanding 9	10
1. Was appointment available when requested?	○	●
2. Time waiting to speak to someone	○	●
3. Vehicle fixed right the first time	○	●
4. Service completed as promised	○	●
5. Service quality	○	●
6. Customer appreciation	○	●

If you cannot answer "Outstanding" (90% - 100%) please contact our Service Manager at (204) 275-4422. Below 90% reflects insufficient customer care in our opinion.

PAYMENT METHOD

MASTERCARD _____
VISA _____
DEBIT CARD _____
CASH _____
AMEX _____

Shop supplies' fees as shown on this invoice include necessary cleaners & degreasers, misc. clips, bolts, fasteners, connectors, lubricants, etc.

WARRANTY

Unless otherwise indicated, TOYOTA parts are warranteed for 24 months or 40,000 kms, whichever comes first.
Labour is covered if the part was installed by a TOYOTA dealer, TOYOTA parts, like batteries, mufflers, shock absorbers and struts, may have different coverage, shown on a label or other document provided to the customer.

CROWN TOYOTA

WAVERLEY AUTOMALL
680 - 1717 WAVERLEY STREET
WINNIPEG, MANITOBA R3T 6A9
TEL: (204) 269-9686 (DIRECT)
FAX: (204) 275-4432
TOLL FREE: 1-866-823-3432
EMAIL: service@CrownToyota.ca
WEBSITE: www.CrownToyota.ca

GST #R8987 66 779

TOIS353960

PRIVACY POLICY

Your privacy is a priority, we pledge continued respect and protection of your personal information. As a TOYOTA owner or lessee, this information is shared between us and Toyota Canada Inc. This allows us to provide ongoing communications that are relevant to you and your vehicle and which enhance your vehicle ownership. All personal information is maintained securely and from time to time may be supplied to third party agencies to ensure that we can serve your needs.

TOIS353960

0201ITOIS353960

ALL ITEMS ARE SUBJECT TO G.S.T.

OUT

INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF $_____ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS, & ACCESSORIES DESCRIBED IN THIS WORK ORDER.

DATE _____ SIGNATURE _____

CUSTOMER NO.	ADVISOR	TAG NO.	INVOICE DATE	INVOICE NO.
10	SHARLIE BOYER 85631	4403	03/19/20	TOIS353960

CROWN TOYOTA
680-1717 WAVERLEY STREET
WINNIPEG, MB R3T 6A9

finmgr1@crowntoyotascion.ca

LABOUR RATE	LICENSE NO.	KILOMETERS	COLOUR	STOCK NO.
139.95	HEA749	27,774	SILVER/	94403

YEAR/MAKE/MODEL	DELIVERY DATE	DELIVERY KMS.
15/TOYOTA/COROLLA/4DR SDN CVT LE		27,500

VEHICLE I.D. NO	SELLING DEALER NO.	IN SERVICE DATE
2 T 1 B U R H E 2 F C 2 7 8 1 6 9	34027	

F.T.E. NO	P.O. NO.	R.O. DATE
		03/18/20

RESIDENCE PHONE	BUSINESS PHONE	COMMENTS
	204-269-1572	MO: 27784

MISC------CODE--------DESCRIPTION----------CONTROL NO---------		
JOB # A SSI SHOP SUPPLIES INTERNAL		51.12
	TOTAL - MISC	51.12

TOTALS----------

CONTROL#	ACCOUNT NUMBER	AMOUNT..
94403	1390	854.22

TOTAL LABOR....	589.66
TOTAL PARTS....	213.44
TOTAL SUBLET...	0.00
TOTAL G.O.G....	0.00
TOTAL MISC.CHG.	51.12
TOTAL MISC.DISC	0.00
TOTAL TAX.....	0.00
TOTAL INVOICE $	**854.22**

_____
APPROVED BY SIGNATURE

THANK YOU

We are striving to keep you Completely Satisfied.

You may soon receive a Service Survey.

	Outstanding 9	10
1. Was appointment available when requested?	○	●
2. Time waiting to speak to someone	○	●
3. Vehicle fixed right the first time	○	●
4. Service completed as promised	○	●
5. Service quality	○	●
6. Customer appreciation	○	●

If you cannot answer "Outstanding" (90% - 100%) please contact our Service Manager at (204) 275-4422. Below 90% reflects insufficient customer care in our opinion.

PAYMENT METHOD

MASTERCARD _____
VISA _____
DEBIT CARD _____
CASH _____
AMEX _____

Shop supplies' fees as shown on this invoice include necessary cleaners & degreasers, misc. clips, bolts, fasteners, connectors, lubricants, etc.

WARRANTY

Unless otherwise indicated, TOYOTA parts are warranteed for 24 months or 40,000 kms, whichever comes first.
Labour is covered if the part was installed by a TOYOTA dealer, TOYOTA parts, like batteries, mufflers, shock absorbers and struts, may have different coverage, shown on a label or other document provided to the customer.

Dilawri's CROWN Auto Group

Internet Service Appointment
www.CrownToyota.ca