



WAVERLEY AUTOMALL
 680 - 1717 WAVERLEY STREET
 WINNIPEG, MANITOBA R3T 6A9
 TEL: (204) 269-9686 (DIRECT)
 FAX: (204) 275-4432
 TOLL FREE: 1-866-823-3432
 EMAIL: service@CrownToyota.ca
 WEBSITE: www.CrownToyota.ca

TOIS360578

PRIVACY POLICY

Your privacy is a priority, we pledge continued respect and protection of your personal information. As a TOYOTA owner or lessee, this information is shared between us and Toyota Canada Inc. This allows us to provide ongoing communications that are relevant to you and your vehicle and which enhance your vehicle ownership. All personal information is maintained securely and from time to time may be supplied to third party agencies to ensure that we can serve your needs

TOIS360578

GST #R8987 66 779



0201IT0IS360578

ALL ITEMS ARE SUBJECT TO G.S.T.

**O
U
T**

INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ _____ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS, & ACCESSORIES DESCRIBED IN THIS WORK ORDER.

DATE _____ SIGNATURE _____

CUSTOMER NO. 10	ADVISOR ALANA HIEBERT	40293	TAG NO. 1681	INVOICE DATE 08/28/20	INVOICE NO. TOIS360578
CROWN TOYOTA 680-1717 WAVERLEY STREET WINNIPEG, MB R3T 6A9 finmgr1@crowntoyotascion.ca	LABOUR RATE 139.95	LICENSE NO.	KILOMETERS 89,696	COLOUR BLACK/	STOCK NO. 2601681
	YEAR/MAKE/MODEL 17/GMC/ACADIA/SLE PWLM CC AC KE CS			DELIVERY DATE	DELIVERY KMS. 89,696
	VEHICLE I.D. NO. 1 G K K N T L S 3 H Z 2 0 7 0 8 2			SELLING DEALER NO.	IN SERVICE DATE
	F.T.E. NO.		P.O. NO.		R.O. DATE 08/24/20
RESIDENCE PHONE	BUSINESS PHONE 204-269-1572	COMMENTS			

MO: 89696

LABOR & PARTS

J# 1 69TOZZ02 GOVERNMENT SAFETY HOURS: 1.50 TECH(S):12282 **189.95**
 CONDITION: PERFORM MANITOBA PROVINCIAL SAFETY \$189.95
 REPAIR ITEMS MUST BE COMPLETED IN 30 DAYS
 (RE-INSPECTION CHARGE OF 19.95 APPLIES)
 CAUSE: SAFETY NUMBER 03073217
 CORRECTION: PERFORMED MB SAFETY INSPECTION

JOB # 1 TOTAL LABOR & PARTS **189.95**

J# 2+01TOZ OIL CHANGE HOURS: TECH(S):103320 **20.71**
 CONDITION: REMOVE AND REPLACE ENGINE OIL & FILTER, INSPECT AIR FILTER,
 LUBRICATE LOCKS, LATCHES, AND HINGES, CHECK LIGHTS, HORN,
 AND WIPERS, CHECK COOLANT, BRAKE, WASHER FLUID LEVELS.
 CHECK AND ADJUST TIRE PRESSURES.
 4CYL & 6CYL (SYNTHETIC)...\$78.98....8CYL (SYNTH)...\$89.98
 CORRECTION: COMPLETED OIL AND FILTER SERVICE

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE
JOB # 2	5	COBBA-05W20-OB	OIL, ENGINE	3.65
JOB # 2	1	ACD-PF63F	OIL FILTER	15.13
JOB # 2 TOTAL PARTS				33.38

JOB # 2 TOTAL LABOR & PARTS **54.09**

J# 3+02TOZ ALIGNMENT HOURS: 1.00 TECH(S):58601 **129.95**
 CONDITION: FOUR WHEEL ALIGNMENT \$129.95
 CORRECTION: COMPLETED FOUR WHEEL ALIGNMENT

JOB # 3 TOTAL LABOR & PARTS **129.95**

MISC	CODE	DESCRIPTION	CONTROL NO
JOB # A	SSI	SHOP SUPPLIES INTERNAL	
TOTAL - MISC			46.73

COMMENTS
2601681

TOTALS

CONTROL#	ACCOUNT NUMBER	AMOUNT..	
2601681	1390	420.72	
TOTAL LABOR....			340.61
TOTAL PARTS....			33.38
TOTAL SUBLET...			0.00
TOTAL G.O.G....			0.00
TOTAL MISC.CHG.			46.73
TOTAL MISC.DISC			0.00
TOTAL TAX.....			0.00

TOTAL INVOICE \$ 420.72

THANK YOU

We are striving to keep you Completely Satisfied. You may soon receive a Service Survey.

	Outstanding	
1. Was appointment available when requested?	9	10
2. Time waiting to speak to someone	<input type="radio"/>	<input checked="" type="radio"/>
3. Vehicle fixed right the first time	<input type="radio"/>	<input checked="" type="radio"/>
4. Service completed as promised	<input type="radio"/>	<input checked="" type="radio"/>
5. Service quality	<input type="radio"/>	<input checked="" type="radio"/>
6. Customer appreciation	<input type="radio"/>	<input checked="" type="radio"/>

If you cannot answer "Outstanding" (90% - 100%) please contact our Service Manager at (204) 275-4422. Below 90% reflects insufficient customer care in our opinion.

PAYMENT METHOD

MASTERCARD _____
 VISA _____
 DEBIT CARD _____
 CASH _____
 AMEX _____

Shop supplies' fees as shown on this invoice include necessary cleaners & degreasers, misc. clips, bolts, fasteners, connectors, lubricants, etc.

WARRANTY

Unless otherwise indicated, TOYOTA parts are warranted for 24 months or 40,000 kms, whichever comes first. Labour is covered if the part was installed by a TOYOTA dealer, TOYOTA parts, like batteries, mufflers, shock absorbers and struts, may have different coverage, shown on a label or other document provided to the customer.

APPROVED BY SIGNATURE

Internet Service Appointment
www.CrownToyota.ca

ACCOUNTING COPY-I

[END OF INVOICE] 11:17am

TDG-CT-SRVINV