



WAVERLEY AUTOMALL  
 680 - 1717 WAVERLEY STREET  
 WINNIPEG, MANITOBA R3T 6A9  
 TEL: (204) 269-9686 (DIRECT)  
 FAX: (204) 275-4432  
 TOLL FREE: 1-866-823-3432  
 EMAIL: service@CrownToyota.ca  
 WEBSITE: www.CrownToyota.ca

**TOIS360966**  
**PRIVACY POLICY**

Your privacy is a priority, we pledge continued respect and protection of your personal information. As a TOYOTA owner or lessee, this information is shared between us and Toyota Canada Inc. This allows us to provide ongoing communications that are relevant to you and your vehicle and which enhance your vehicle ownership. All personal information is maintained securely and from time to time may be supplied to third party agencies to ensure that we can serve your needs.

TOIS360966

GST #R8987 66 779



0201IT0IS360966

ALL ITEMS ARE SUBJECT TO G.S.T.

O  
U  
T

INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ \_\_\_\_\_ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS, & ACCESSORIES DESCRIBED IN THIS WORK ORDER.

DATE \_\_\_\_\_ SIGNATURE \_\_\_\_\_

CUSTOMER NO. <b>10</b>	ADVISOR <b>ALANA HIEBERT</b>	40293	TAG NO. <b>4664</b>	INVOICE DATE <b>09/17/20</b>	TOIS360966
<b>CROWN TOYOTA</b> 680-1717 WAVERLEY STREET WINNIPEG, MB R3T 6A9	LABOUR RATE <b>139.95</b>	LICENSE NO. <b>HWS251</b>	KILOMETERS <b>103,079</b>	COLOR <b>BEIGE/</b>	STOCK NO. <b>94664</b>
finmgr1@crowntoyotascion.ca	YEAR/MAKE/MODEL <b>15/TOYOTA/CAMRY/4DR SDN I4 AUTO LE</b>	VEHICLE I.D. NO. <b>4 T 1 B F 1 F K 4 F U 0 7 2 9 8 4</b>		DELIVERY DATE	DELIVERY KMS. <b>103,079</b>
RESIDENCE PHONE	BUSINESS PHONE <b>204-269-1572</b>	F.T.E. NO.	P.O. NO.	P.O. DATE <b>09/01/20</b>	COMMENTS <b>M0: 103081</b>

**LABOR & PARTS**

**J# 1 69TOZZ02 GOVERNMENT SAFETY HOURS: 1.50 TECH(S):68812 189.95**  
 CONDITION: PERFORM MANITOBA PROVINCIAL SAFETY \$189.95  
 REPAIR ITEMS MUST BE COMPLETED IN 30 DAYS  
 (RE-INSPECTION CHARGE OF 19.95 APPLIES)  
 CAUSE: SAFETY NUMBER 03089625  
 CORRECTION: PERFORMED MB SAFETY INSPECTION

JOB # 1 TOTAL LABOR & PARTS 189.95

**J# 2+11TOZZ21 OIL PRESSURE SWITCH HOURS: 0.60 TECH(S):68812 83.97**  
 CONDITION: UPON INSPECTION IT WAS NOTED THAT THE OILPRESSURE SWITCH WAS LEAKING  
 CAUSE: LEAKING OIL  
 CORRECTION: REPLACED LEAKING OIL PRESSURE SWITCH INSTALLED WITH TEFLON TAPE

PARTS-----QTY---FP-NUMBER-----DESCRIPTION-----UNIT PRICE-	
JOB # 2 1 83530-0E010 SWITCH ASSEMBLY,	95.09 95.09
	JOB # 2 TOTAL PARTS 95.09
	JOB # 2 TOTAL LABOR & PARTS 179.06

**J# 3+18TOZZ10 ROTORS (FRONT) HOURS: TECH(S):68812 139.95**  
 CONDITION: REMOVE AND REPLACE THE FRONT ROOTRS  
 CORRECTION: REPLACED ROTORS

PARTS-----QTY---FP-NUMBER-----DESCRIPTION-----UNIT PRICE-	
JOB # 3 2 43512-06150 ROTOR, BRAKE FRON	89.95 179.90
	ROTORS COMING IN TOM 09/10
	JOB # 3 TOTAL PARTS 179.90
	JOB # 3 TOTAL LABOR & PARTS 319.85

**J# 4+18TOZZ22 REAR BRAKE PADS HOURS: TECH(S):68812 139.95**  
 CONDITION: INSTALL REAR TOYOTA GENUINE BRAKE PADS  
 SERVICE ROTORS, CLEAN AND ADJUST CALIPERS  
 ..... \$139.95 PLUS PARTS  
 CORRECTION: INSTALLED NEW REAR BRAKE PADS

PARTS-----QTY---FP-NUMBER-----DESCRIPTION-----UNIT PRICE-	
JOB # 4 1 04466-06200 PAD KIT, DISC BRA	114.95 114.95
	JOB # 4 TOTAL PARTS 114.95
	JOB # 4 TOTAL LABOR & PARTS 254.90

**J# 5+01TOZ OIL CHANGE HOURS: TECH(S):68812 20.71**  
 CONDITION: REMOVE AND REPLACE ENGINE OIL & FILTER, INSPECT AIR FILTER, LUBRICATE LOCKS, LATCHES, AND HINGES, CHECK LIGHTS, HORN, AND WIPERS, CHECK COOLANT, BRAKE, WASHER FLUID LEVELS. CHECK AND ADJUST TIRE PRESSURES.  
 4CYL & 6CYL (SYNTHETIC)...\$78.98....8CYL (SYNTH)...\$89.98  
 CORRECTION: COMPLETED OIL AND FILTER SERVICE

**THANK YOU**

We are striving to keep you Completely Satisfied. You may soon receive a Service Survey.

	Outstanding
1. Was appointment available when requested? .....	9 <input type="radio"/> 10 <input checked="" type="radio"/>
2. Time waiting to speak to someone .....	<input type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/>
3. Vehicle fixed right the first time .....	<input type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/>
4. Service completed as promised .....	<input type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/>
5. Service quality .....	<input type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/>
6. Customer appreciation .....	<input type="radio"/> <input checked="" type="radio"/> <input checked="" type="radio"/>

If you cannot answer "Outstanding" (90% - 100%) please contact our Service Manager at (204) 275-4422. Below 90% reflects insufficient customer care in our opinion.

**PAYMENT METHOD**

**MASTERCARD** \_\_\_\_\_

**VISA** \_\_\_\_\_

**DEBIT CARD** \_\_\_\_\_

**CASH** \_\_\_\_\_

**AMEX** \_\_\_\_\_

Shop supplies' fees as shown on this invoice include necessary cleaners & degreasers, misc. clips, bolts, fasteners, connectors, lubricants, etc.

**WARRANTY**

Unless otherwise indicated, TOYOTA parts are warranted for 24 months or 40,000 kms, whichever comes first. Labour is covered if the part was installed by a TOYOTA dealer, TOYOTA parts, like batteries, mufflers, shock absorbers and struts, may have different coverage, shown on a label or other document provided to the customer.

*Internet Service Appointment*  
**www.CrownToyota.ca**

ACCOUNTING COPY-I

[CONTINUED ON NEXT PAGE]

09:41am

TDG-CT-SRVINV





WAVERLEY AUTOMALL  
 680 - 1717 WAVERLEY STREET  
 WINNIPEG, MANITOBA R3T 6A9  
 TEL: (204) 269-9686 (DIRECT)  
 FAX: (204) 275-4432  
 TOLL FREE: 1-866-823-3432  
 EMAIL: service@CrownToyota.ca  
 WEBSITE: www.CrownToyota.ca

**TOIS360966**

**PRIVACY POLICY**

Your privacy is a priority, we pledge continued respect and protection of your personal information. As a TOYOTA owner or lessee, this information is shared between us and Toyota Canada Inc. This allows us to provide ongoing communications that are relevant to you and your vehicle and which enhance your vehicle ownership. All personal information is maintained securely and from time to time may be supplied to third party agencies to ensure that we can serve your needs.

TOIS360966

GST #R8987 66 779



0201IT0IS360966

ALL ITEMS ARE SUBJECT TO G.S.T.

O  
U  
T

INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ \_\_\_\_\_ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS, & ACCESSORIES DESCRIBED IN THIS WORK ORDER.

DATE \_\_\_\_\_ SIGNATURE \_\_\_\_\_

CUSTOMER NO. <b>10</b>	ADVISOR <b>ALANA HIEBERT</b>	40293	TAG NO. <b>4664</b>	INVOICE DATE <b>09/17/20</b>	INVOICE NO. <b>TOIS360966</b>
CROWN TOYOTA 680-1717 WAVERLEY STREET WINNIPEG, MB R3T 6A9	LABOUR RATE <b>139.95</b>	LICENSE NO. <b>HWS251</b>	KILOMETERS <b>103,079</b>	COLOR <b>BEIGE/</b>	STOCK NO. <b>94664</b>
	YEAR/MAKE/MODEL <b>15/TOYOTA/CAMRY/4DR SDN I4 AUTO LE</b>			DELIVERY DATE	DELIVERY KMS. <b>103,079</b>
	VEHICLE I.D. NO. <b>4 T 1 B F 1 F K 4 F U 0 7 2 9 8 4</b>			SELLING DEALER NO. <b>53009</b>	IN SERVICE DATE
	F.T.E. NO.		P.O. NO.		R.O. DATE <b>09/01/20</b>
RESIDENCE PHONE	BUSINESS PHONE <b>204-269-1572</b>	COMMENTS <b>MO: 103081</b>			
finmgr1@crowntoyotascion.ca					

PARTS	QTY	FP	NUMBER	DESCRIPTION	UNIT PRICE	PRICE
JOB # 5	1		PKYZZA1-0W20	OIL CHANGE	44.24	44.24
JOB # 5	1		90430-12028	GASKET	****	****
JOB # 5	1		04152-YZZA1	REPLACEABLE ELEME	****	****
JOB # 5	6		COBBA-0W2SN-0B	0W20 GF5	****	****
JOB # 5 TOTAL PARTS						44.24
JOB # 5 TOTAL LABOR & PARTS						64.95

MISC	CODE	DESCRIPTION	CONTROL NO	PRICE
JOB # A	SSI	SHOP SUPPLIES INTERNAL		51.12
TOTAL - MISC				51.12

COMMENTS-----  
 94664

TOTALS-----		
CONTROL#	ACCOUNT NUMBER	AMOUNT..
94664	1390	1059.83
	TOTAL LABOR....	574.53
	TOTAL PARTS....	434.18
	TOTAL SUBLET...	0.00
	TOTAL G.O.G....	0.00
	TOTAL MISC.CHG.	51.12
	TOTAL MISC.DISC	0.00
	TOTAL TAX.....	0.00
<b>TOTAL INVOICE \$</b>		<b>1059.83</b>

**THANK YOU**

We are striving to keep you Completely Satisfied. You may soon receive a Service Survey.

	Outstanding
1. Was appointment available when requested? .....	9 <input type="radio"/> 10 <input checked="" type="radio"/>
2. Time waiting to speak to someone .....	<input type="radio"/> <input checked="" type="radio"/>
3. Vehicle fixed right the first time .....	<input type="radio"/> <input checked="" type="radio"/>
4. Service completed as promised .....	<input type="radio"/> <input checked="" type="radio"/>
5. Service quality .....	<input type="radio"/> <input checked="" type="radio"/>
6. Customer appreciation .....	<input type="radio"/> <input checked="" type="radio"/>

If you cannot answer "Outstanding" (90% - 100%) please contact our Service Manager at (204) 275-4422. Below 90% reflects insufficient customer care in our opinion.

**PAYMENT METHOD**


**MASTERCARD** \_\_\_\_\_  
**VISA** \_\_\_\_\_  
**DEBIT CARD** \_\_\_\_\_  
**CASH** \_\_\_\_\_  
**AMEX** \_\_\_\_\_

Shop supplies' fees as shown on this invoice include necessary cleaners & degreasers, misc. clips, bolts, fasteners, connectors, lubricants, etc.

**WARRANTY**

Unless otherwise indicated, TOYOTA parts are warranted for 24 months or 40,000 kms, whichever comes first. Labour is covered if the part was installed by a TOYOTA dealer, TOYOTA parts, like batteries, mufflers, shock absorbers and struts, may have different coverage, shown on a label or other document provided to the customer.

APPROVED BY SIGNATURE



*Internet Service Appointment*  
**www.CrownToyota.ca**

ACCOUNTING COPY-I

[ END OF INVOICE ] 09:41am