



WAVERLEY AUTOMALL
 680 - 1717 WAVERLEY STREET
 WINNIPEG, MANITOBA R3T 6A9
 TEL: (204) 269-9686 (DIRECT)
 FAX: (204) 275-4432
 TOLL FREE: 1-866-823-3432
 EMAIL: service@CrownToyota.ca
 WEBSITE: www.CrownToyota.ca

TOIS366102

PRIVACY POLICY

Your privacy is a priority, we pledge continued respect and protection of your personal information. As a TOYOTA owner or lessee, this information is shared between us and Toyota Canada Inc. This allows us to provide ongoing communications that are relevant to you and your vehicle and which enhance your vehicle ownership. All personal information is maintained securely and from time to time may be supplied to third party agencies to ensure that we can serve your needs.

TOIS366102

GST #R8987 66 779



0201IT0IS366102

ALL ITEMS ARE SUBJECT TO G.S.T.

OUT

INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ _____ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS, & ACCESSORIES DESCRIBED IN THIS WORK ORDER.

DATE _____ SIGNATURE _____

CUSTOMER NO. 10	ADVISOR ALANA HIEBERT	40293	TAG NO. 3291	INVOICE DATE 12/23/20	INVOICE NO. TOIS366102
CROWN TOYOTA 680-1717 WAVERLEY STREET WINNIPEG, MB R3T 6A9	LABOUR RATE 139.95	LICENSE NO.	KILOMETERS 51,816	COLOUR 0218 ATTITU	STOCK NO. 2603291
	YEAR/MAKE/MODEL 15/TOYOTA/CAMRY/LE 4DR PWLM CC AC KE			DELIVERY DATE	DELIVERY KMS. 51,681
	VEHICLE I.D. NO. 4 T 1 B F 1 F K 6 F U 9 6 2 1 6 1			SELLING DEALER NO. 34014	IN SERVICE DATE 05/08/15
finmgr1@crowntoyotascion.ca	F.T.E. NO.		PO. NO.	R.O. DATE 12/23/20	
RESIDENCE PHONE	BUSINESS PHONE 204-269-1572	COMMENTS E# ASV50L-CETNKA			M0: 51818

LABOR & PARTS
J# 1 69TOZZ02 GOVERNMENT SAFETY HOURS: 1.50 TECH(S):36097 189.95
 CONDITION: PERFORM MANITOBA PROVINCIAL SAFETY \$189.95
 REPAIR ITEMS MUST BE COMPLETED IN 30 DAYS
 (RE-INSPECTION CHARGE OF 19.95 APPLIES)
 CAUSE: SAFETY NUMBER 03137006
 CORRECTION: PERFORMED MB SAFETY INSPECTION
 JOB # 1 TOTAL LABOR & PARTS 189.95

J# 2+09TOZCABIN CABIN FILTER HOURS: TECH(S):36097 20.04
 CONDITION: AFTER INSPECTION, CABIN FILTER NEEDS REPLACEMENT.
 INSTALL PRICE \$69.95 PLUS TAXES AND FEES.
 CAUSE: CABIN FILTER FOUND TO BE PLUGGED WITH DIRT AND DUST.
 CORRECTION: REMOVE OLD CABIN FILTER, NEW CABIN FILTER INSTALLED.
 PARTS-----QTY---FP-NUMBER-----DESCRIPTION-----UNIT PRICE-
 JOB # 2 1 87139-YZZ20 ELEMENT, AIR REFI 32.95 32.95
 JOB # 2 TOTAL PARTS 32.95
 JOB # 2 TOTAL LABOR & PARTS 52.99

J# 3+09TOZZ-AF AIR FILTER HOURS: TECH(S):36097 20.04
 CONDITION: REPLACE THE ENGINE AIR FILTER
 CORRECTION: REPLACED AIR FILTER.
 PARTS-----QTY---FP-NUMBER-----DESCRIPTION-----UNIT PRICE-
 JOB # 3 1 17801-YZZ02 ELEMENT SUB-ASSEM 19.95 19.95
 JOB # 3 TOTAL PARTS 19.95
 JOB # 3 TOTAL LABOR & PARTS 39.99

J# 4+01TOZ OIL CHANGE HOURS: TECH(S):36097 20.71
 CONDITION: REMOVE AND REPLACE ENGINE OIL & FILTER, INSPECT AIR FILTER,
 LUBRICATE LOCKS, LATCHES, AND HINGES, CHECK LIGHTS, HORN,
 AND WIPERS, CHECK COOLANT, BRAKE, WASHER FLUID LEVELS.
 CHECK AND ADJUST TIRE PRESSURES.
 4CYL & 6CYL (SYNTHETIC)...\$78.98...8CYL (SYNTH)...\$89.98
 CORRECTION: COMPLETED OIL AND FILTER SERVICE
 PARTS-----QTY---FP-NUMBER-----DESCRIPTION-----UNIT PRICE-
 JOB # 4 1 PKYZZA1-0W20 OIL CHANGE 44.24 44.24
 JOB # 4 1 90430-12028 GASKET ****
 JOB # 4 1 04152-YZZA1 REPLACEABLE ELEME ****
 JOB # 4 6 COBBA-0W2SN-0B OW20 GF5 ****
 JOB # 4 TOTAL PARTS 44.24
 JOB # 4 TOTAL LABOR & PARTS 64.95

J# 5+09TOZZ17A WIPER BLADES HOURS: TECH(S):36097 0.00
 CONDITION: INSTALL WIPER BLADES
 CORRECTION: INSTALLED WIPER BLADES

THANK YOU

We are striving to keep you Completely Satisfied. You may soon receive a Service Survey.

Outstanding

1. Was appointment available when requested?	9	10
2. Time waiting to speak to someone	<input type="radio"/>	<input checked="" type="radio"/>
3. Vehicle fixed right the first time	<input type="radio"/>	<input checked="" type="radio"/>
4. Service completed as promised	<input type="radio"/>	<input checked="" type="radio"/>
5. Service quality	<input type="radio"/>	<input checked="" type="radio"/>
6. Customer appreciation	<input type="radio"/>	<input checked="" type="radio"/>

If you cannot answer "Outstanding" (90% - 100%) please contact our Service Manager at (204) 275-4422. Below 90% reflects insufficient customer care in our opinion.

PAYMENT METHOD

MASTERCARD _____

VISA _____

DEBIT CARD _____

CASH _____

AMEX _____

Shop supplies' fees as shown on this invoice include necessary cleaners & degreasers, misc. clips, bolts, fasteners, connectors, lubricants, etc.

WARRANTY

Unless otherwise indicated, TOYOTA parts are warranted for 24 months or 40,000 kms, whichever comes first. Labour is covered if the part was installed by a TOYOTA dealer, TOYOTA parts, like batteries, mufflers, shock absorbers and struts, may have different coverage, shown on a label or other document provided to the customer.

Internet Service Appointment
www.CrownToyota.ca

TDG-CIT-SRVINV



WAVERLEY AUTOMALL
 680 - 1717 WAVERLEY STREET
 WINNIPEG, MANITOBA R3T 6A9
 TEL: (204) 269-9686 (DIRECT)
 FAX: (204) 275-4432
 TOLL FREE: 1-866-823-3432
 EMAIL: service@CrownToyota.ca
 WEBSITE: www.CrownToyota.ca

TOIS366102

PRIVACY POLICY

Your privacy is a priority, we pledge continued respect and protection of your personal information. As a TOYOTA owner or lessee, this information is shared between us and Toyota Canada Inc. This allows us to provide ongoing communications that are relevant to you and your vehicle and which enhance your vehicle ownership. All personal information is maintained securely and from time to time may be supplied to third party agencies to ensure that we can serve your needs.

TOIS366102

GST #R8987 66 779



0201IT0IS366102

ALL ITEMS ARE SUBJECT TO G.S.T.

OUT

INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ _____ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS, & ACCESSORIES DESCRIBED IN THIS WORK ORDER.

DATE _____ SIGNATURE _____

CUSTOMER NO. 10	ADVISOR ALANA HIEBERT	40293	TAG NO. 3291	INVOICE DATE 12/23/20	INVOICE NO. TOIS366102
CROWN TOYOTA 680-1717 WAVERLEY STREET WINNIPEG, MB R3T 6A9	LABOUR RATE 139.95	LICENSE NO.	KILOMETERS 51,816	COLOUR 0218 ATTITU	STOCK NO. 2603291
	YEAR/MAKE/MODEL 15/TOYOTA/CAMRY/LE 4DR PWLM CC AC KE			DELIVERY DATE	DELIVERY KMS. 51,681
	VEHICLE I.D. NO. 4 T 1 B F 1 F K 6 F U 9 6 2 1 6 1			SELLING DEALER NO. 34014	IN SERVICE DATE 05/08/15
	F.T.E. NO.		P.O. NO.	R.O. DATE 12/23/20	
finmgr1@crowntoyotascion.ca	RESIDENCE PHONE	BUSINESS PHONE 204-269-1572	COMMENTS E# ASV50L-CETNKA		M0: 51818

PARTS	QTY	FP	NUMBER	DESCRIPTION	UNIT PRICE	PRICE
JOB # 5	1		C0222-WTR26	BLADE,WIPER	18.50	18.50
JOB # 5	1		C0222-WTR18	BLADE,WIPER	18.50	18.50
JOB # 5 TOTAL PARTS						37.00
JOB # 5 TOTAL LABOR & PARTS						37.00

J# 6+18TOZZ12C 4WHEEL BRK SERVICE HOURS: TECH(S):36097 **164.95**

CONDITION: CLEAN, LUBRICATE AND ADJUST BRAKES AND/OR EMERGENCY BRAKE SYSTEM, INSPECT CYLINDERS, HOSES AND LINES. REMOVE ALL HARDWARE AND CLIPS, GRIND CORROSION OFF ROTORS AND OR DRUMS, LUBRICATE AS NECESSARY, DEGLAZE REAR SHOES AND OR ALL PADS

CAUSE: CONSTANT EXPOSURE TO THE ELEMENTS MAY RESULT IN RUST BUILD-UP, WHICH CAN CAUSE BRAKE DRAGGING, PULLING, PULSATING, AND/OR ABNORMAL NOISE. REGULAR LUBRICATION AND CLEANING OF BRAKING SYSTEM COMPONENTS HELPS ENSURE PROPER FUNCTION AND REDUCE PREMATURE WEAR.

CORRECTION: COMPLETED 4 WHEEL BRAKE SERVICE. LUBRICATED CALIPERS, SLIDERS AND PINS. DEGLAZE ROTORS AND DRUMS.

JOB # 6 TOTAL LABOR & PARTS **164.95**

J# 7+18TOZZ01 BRAKE FLUID FLUSH HOURS: TECH(S):36097 **122.03**

CONDITION: POWER VACUUM AND BLEED HYDRAULIC SYSTEM AND REPLACE WITH GENUINE TOYOTA BRAKE FLUID. INSPECT HYDRAULIC LINES AND HOSES

CORRECTION: COMPLETED BRAKE FLUID FLUSH

JOB # 7 TOTAL LABOR & PARTS **129.19**

J# 8+02TOZ ALIGNMENT HOURS: 1.00 TECH(S):100632 **129.95**

CONDITION: FOUR WHEEL ALIGNMENT \$129.95

CORRECTION: COMPLETE FOUR WHEEL ALIGNMENT

JOB # 8 TOTAL LABOR & PARTS **129.95**

MISC	CODE	DESCRIPTION	CONTROL NO	PRICE
JOB # A	SSI	SHOP SUPPLIES INTERNAL		51.12
TOTAL - MISC				51.12

COMMENTS
2603291

THANK YOU

We are striving to keep you Completely Satisfied. You may soon receive a Service Survey.

	Outstanding
1. Was appointment available when requested?	9 10
2. Time waiting to speak to someone	<input type="radio"/> <input checked="" type="radio"/>
3. Vehicle fixed right the first time	<input type="radio"/> <input checked="" type="radio"/>
4. Service completed as promised	<input type="radio"/> <input checked="" type="radio"/>
5. Service quality	<input type="radio"/> <input checked="" type="radio"/>
6. Customer appreciation	<input type="radio"/> <input checked="" type="radio"/>

If you cannot answer "Outstanding" (90% - 100%) please contact our Service Manager at (204) 275-4422. Below 90% reflects insufficient customer care in our opinion.

PAYMENT METHOD

MASTERCARD _____

VISA _____

DEBIT CARD _____

CASH _____

AMEX _____

Shop supplies' fees as shown on this invoice include necessary cleaners & degreasers, misc. clips, bolts, fasteners, connectors, lubricants, etc.

WARRANTY

Unless otherwise indicated, TOYOTA parts are warranted for 24 months or 40,000 kms, whichever comes first. Labour is covered if the part was installed by a TOYOTA dealer, TOYOTA parts, like batteries, mufflers, shock absorbers and struts, may have different coverage, shown on a label or other document provided to the customer.

Internet Service Appointment
www.CrownToyota.ca

TDG-CT-SRVINV



WAVERLEY AUTOMALL
 680 - 1717 WAVERLEY STREET
 WINNIPEG, MANITOBA R3T 6A9
 TEL: (204) 269-9686 (DIRECT)
 FAX: (204) 275-4432
 TOLL FREE: 1-866-823-3432
 EMAIL: service@CrownToyota.ca
 WEBSITE: www.CrownToyota.ca

TOIS366102
 PRIVACY POLICY

Your privacy is a priority, we pledge continued respect and protection of your personal information. As a TOYOTA owner or lessee, this information is shared between us and Toyota Canada Inc. This allows us to provide ongoing communications that are relevant to you and your vehicle and which enhance your vehicle ownership. All personal information is maintained securely and from time to time may be supplied to third party agencies to ensure that we can serve your needs.

TOIS366102

GST #R8987 66 779



0201ITOIS366102

ALL ITEMS ARE SUBJECT TO G.S.T.

**O
U
T**

INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ _____ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS, & ACCESSORIES DESCRIBED IN THIS WORK ORDER.

DATE _____ SIGNATURE _____

CUSTOMER NO. 10	ADVISOR ALANA HIEBERT	40293	TAG NO. 3291	INVOICE DATE 12/23/20	INVOICE NO. TOIS366102
CROWN TOYOTA 680-1717 WAVERLEY STREET WINNIPEG, MB R3T 6A9 finmgr1@crowntoyotascion.ca	LABOUR RATE 139.95	LICENSE NO.	KILOMETERS 51,816	COLOUR 0218 ATTITU	STOCK NO. 2603291
	YEAR/MAKE/MODEL 15/TOYOTA/CAMRY/LE 4DR PWLM CC AC KE			DELIVERY DATE	DELIVERY KMS. 51,681
	VEHICLE I.D. NO 4 T 1 B F 1 F K 6 F U 9 6 2 1 6 1			SELLING DEALER NO. 34014	IN SERVICE DATE 05/08/15
	F.T.E. NO		P.O. NO.	R.O. DATE 12/23/20	
RESIDENCE PHONE	BUSINESS PHONE 204-269-1572	COMMENTS E# ASV50L-CETNKA		M0: 51818	

TOTALS		
CONTROL#	ACCOUNT NUMBER	AMOUNT..
2603291	1390	860.09
	TOTAL LABOR....	667.67
	TOTAL PARTS....	141.30
	TOTAL SUBLET...	0.00
	TOTAL G.O.G....	0.00
	TOTAL MISC.CHG.	51.12
	TOTAL MISC.DISC	0.00
	TOTAL TAX.....	0.00
TOTAL INVOICE \$		860.09

THANK YOU

We are striving to keep you Completely Satisfied. You may soon receive a Service Survey.

- | | |
|--|--|
| | Outstanding |
| 1. Was appointment available when requested? | 9 10 |
| 2. Time waiting to speak to someone | <input type="radio"/> <input checked="" type="radio"/> |
| 3. Vehicle fixed right the first time | <input type="radio"/> <input checked="" type="radio"/> |
| 4. Service completed as promised | <input type="radio"/> <input checked="" type="radio"/> |
| 5. Service quality | <input type="radio"/> <input checked="" type="radio"/> |
| 6. Customer appreciation | <input type="radio"/> <input checked="" type="radio"/> |

If you cannot answer "Outstanding" (90% - 100%) please contact our Service Manager at (204) 275-4422. Below 90% reflects insufficient customer care in our opinion.

PAYMENT METHOD

- MASTERCARD _____
- VISA _____
- DEBIT CARD _____
- CASH _____
- AMEX _____

Shop supplies' fees as shown on this invoice include necessary cleaners & degreasers, misc. clips, bolts, fasteners, connectors, lubricants, etc.

WARRANTY

Unless otherwise indicated, TOYOTA parts are warranted for 24 months or 40,000 kms, whichever comes first. Labour is covered if the part was installed by a TOYOTA dealer, TOYOTA parts, like batteries, mufflers, shock absorbers and struts, may have different coverage, shown on a label or other document provided to the customer.

Internet Service Appointment
www.CrownToyota.ca

ACCOUNTING COPY-I

[END OF INVOICE] 11:35am

TDG-CT-SRVINV