



WAVERLEY AUTOMALL
 680 - 1717 WAVERLEY STREET
 WINNIPEG, MANITOBA R3T 6A9
 TEL: (204) 269-9686 (DIRECT)
 FAX: (204) 275-4432
 TOLL FREE: 1-866-823-3432
 EMAIL: service@CrownToyota.ca
 WEBSITE: www.CrownToyota.ca

TOIS372178

PRIVACY POLICY

Your privacy is a priority, we pledge continued respect and protection of your personal information. As a TOYOTA owner or lessee, this information is shared between us and Toyota Canada Inc. This allows us to provide ongoing communications that are relevant to you and your vehicle and which enhance your vehicle ownership. All personal information is maintained securely and from time to time may be supplied to third party agencies to ensure that we can serve your needs.

TOIS372178

GST #R8987 66 779



0201IT0IS372178

ALL ITEMS ARE SUBJECT TO G.S.T.

OUT

INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ _____ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS, & ACCESSORIES DESCRIBED IN THIS WORK ORDER.
 DATE _____ SIGNATURE _____

CUSTOMER NO. 10	ADVISOR ALANA HIEBERT	TAG NO. 40293 5231	INVOICE DATE 05/10/21	INVOICE NO. TOIS372178
CROWN TOYOTA 680-1717 WAVERLEY STREET WINNIPEG, MB R3T 6A9	LABOUR RATE 139.95	LICENSE NO.	COLOUR 01J9 CELEST	STOCK NO. 2515231
	YEAR/MAKE/MODEL 19/TOYOTA/AVALON/4DR SDN LIMITED AT	KILOMETERS 10,700	DELIVERY DATE	DELIVERY KMS. 10,700
	VEHICLE I.D. NO. 4 T 1 B Z 1 F B 1 K U 0 1 4 3 8 1	F.T.E. NO. 898766779MT0003	SELLING DEALER NO. 34031	IN SERVICE DATE 08/02/18
	R.O. DATE 05/10/21	R.O. DATE		
RESIDENCE PHONE	BUSINESS PHONE 204-269-1572	COMMENTS E# GSX50L-AEZPBA	MO: 10701	

LABOR & PARTS-----
J# 1 69TOZZ02 GOVERNMENT SAFETY HOURS: 1.50 TECH(S):68812 189.95
 CONDITION: PERFORM MANITOBA PROVINCIAL SAFETY \$189.95
 REPAIR ITEMS MUST BE COMPLETED IN 30 DAYS
 (RE-INSPECTION CHARGE OF 19.95 APPLIES)
 CAUSE: SAFETY NUMBER 03164758
 CORRECTION: PERFORMED MB SAFETY INSPECTION
 JOB # 1 TOTAL LABOR & PARTS 189.95

J# 2 69TOZZ01 T.C.U.V. CERTIFIED HOURS: 1.00 TECH(S):68812 125.00
 CONDITION: PERFORM TCUV INSPECTION.
 COMPLETE FORM.
 PROVIDE PAPERWORK TO SERVICE MANAGER
 CAUSE: J 116558
 CORRECTION: COMPLETED THE TCUV INSPECTION
 JOB # 2 TOTAL LABOR & PARTS 125.00

J# 3+01TOZ OIL CHANGE HOURS: TECH(S):68812 30.71
 CONDITION: REMOVE AND REPLACE ENGINE OIL & FILTER, INSPECT AIR FILTER,
 LUBRICATE LOCKS, LATCHES, AND HINGES, CHECK LIGHTS, HORN,
 AND WIPERS, CHECK COOLANT, BRAKE, WASHER FLUID LEVELS.
 CHECK AND ADJUST TIRE PRESSURES.
 4CYL & 6CYL (SYNTHETIC)...\$78.98...8CYL (SYNTH)...\$89.98
 CORRECTION: COMPLETED OIL AND FILTER SERVICE

PARTS-----QTY-----FP-NUMBER-----DESCRIPTION-----UNIT PRICE-				
JOB # 3 1 PKYZZA1-0W20 OIL CHANGE	44.24	44.24	****	
JOB # 3 1 90430-12028 GASKET	****	****	****	
JOB # 3 1 04152-YZZA1 REPLACEABLE ELEME	****	****	****	
JOB # 3 6 COBBA-0W2SN-0B 0W20 GF5	****	****	****	
JOB # 3 TOTAL PARTS			44.24	
JOB # 3 TOTAL LABOR & PARTS			74.95	

J# 4+09TOZCABIN CABIN FILTER HOURS: TECH(S):68812 25.04
 CONDITION: AFTER INSPECTION, CABIN FILTER NEEDS REPLACEMENT.
 INSTALL PRICE \$69.95 PLUS TAXES AND FEES.
 CAUSE: CABIN FILTER FOUND TO BE PLUGGED WITH DIRT AND DUST.
 CORRECTION: REMOVE OLD CABIN FILTER, NEW CABIN FILTER INSTALLED.

PARTS-----QTY-----FP-NUMBER-----DESCRIPTION-----UNIT PRICE-				
JOB # 4 1 87139-0R030 ELEMENT, AIR REFI	32.95	32.95		
JOB # 4 TOTAL PARTS			32.95	
JOB # 4 TOTAL LABOR & PARTS			57.99	

J# 5+02TOZ ALIGNMENT HOURS: 1.00 TECH(S):100632 129.95
 CONDITION: FOUR WHEEL ALIGNMENT \$129.95
 CORRECTION: COMPLETED FOUR WHEEL ALIGNMENT
 JOB # 5 TOTAL LABOR & PARTS 129.95

Internet Service Appointment
www.CrownToyota.ca

THANK YOU

We are striving to keep you Completely Satisfied. You may soon receive a Service Survey.

Outstanding

1. Was appointment available when requested?	<input type="radio"/>	9	<input type="radio"/>	10
2. Time waiting to speak to someone	<input type="radio"/>		<input type="radio"/>	
3. Vehicle fixed right the first time	<input type="radio"/>		<input type="radio"/>	
4. Service completed as promised	<input type="radio"/>		<input type="radio"/>	
5. Service quality	<input type="radio"/>		<input type="radio"/>	
6. Customer appreciation	<input type="radio"/>		<input type="radio"/>	

If you cannot answer "Outstanding" (90% - 100%) please contact our Service Manager at (204) 275-4422. Below 90% reflects insufficient customer care in our opinion.

PAYMENT METHOD

MASTERCARD _____

VISA _____

DEBIT CARD _____

CASH _____

AMEX _____

Shop supplies' fees as shown on this invoice include necessary cleaners & degreasers, misc. clips, bolts, fasteners, connectors, lubricants, etc.

WARRANTY

Unless otherwise indicated, TOYOTA parts are warranted for 24 months or 40,000 kms, whichever comes first.
 Labour is covered if the part was installed by a TOYOTA dealer, TOYOTA parts, like batteries, mufflers, shock absorbers and struts, may have different coverage, shown on a label or other document provided to the customer.

TDG-CT-SRVINV



WAVERLEY AUTOMALL
 680 - 1717 WAVERLEY STREET
 WINNIPEG, MANITOBA R3T 6A9
 TEL: (204) 269-9686 (DIRECT)
 FAX: (204) 275-4432
 TOLL FREE: 1-866-823-3432
 EMAIL: service@CrownToyota.ca
 WEBSITE: www.CrownToyota.ca

GST #R8987 66 779

TOIS372178

PRIVACY POLICY

Your privacy is a priority, we pledge continued respect and protection of your personal information. As a TOYOTA owner or lessee, this information is shared between us and Toyota Canada Inc. This allows us to provide ongoing communications that are relevant to you and your vehicle and which enhance your vehicle ownership. All personal information is maintained securely and from time to time may be supplied to third party agencies to ensure that we can serve your needs.

TOIS372178



0201IT0IS372178

ALL ITEMS ARE SUBJECT TO G.S.T.

OUT

INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ _____ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS, & ACCESSORIES DESCRIBED IN THIS WORK ORDER.
 DATE _____ SIGNATURE _____

CUSTOMER NO. 10	ADVISOR ALANA HIEBERT	TAG NO. 40293 5231	INVOICE DATE 05/10/21	INVOICE NO. TOIS372178
CROWN TOYOTA 680-1717 WAVERLEY STREET WINNIPEG, MB R3T 6A9 finmgr1@crowntoyotascion.ca	LABOUR RATE 139.95	LICENSE NO.	KILOMETERS 10,700	COLOUR 01J9 CELEST
	YEAR/MAKE/MODEL 19/TOYOTA/AVALON/4DR SDN LIMITED AT			STOCK NO. 2515231
	VEHICLE I.D. NO. 4 T 1 B Z 1 F B 1 K U 0 1 4 3 8 1			DELIVERY DATE
	F.T.E. NO. 898766779MT0003	PO. NO.		DELIVERY KMS. 10,700
RESIDENCE PHONE	BUSINESS PHONE 204-269-1572	COMMENTS E# GSX50L-AEZPBA		
				MO: 10701

MISC-----CODE-----	DESCRIPTION-----	CONTROL NO-----	
JOB # A	SSI SHOP SUPPLIES INTERNAL		
			51.12
			TOTAL - MISC 51.12

COMMENTS-----
 2515231

TOTALS-----			
CONTROL#	ACCOUNT NUMBER	AMOUNT..	
2515231	1390	628.96	
			TOTAL LABOR.... 500.65
			TOTAL PARTS.... 77.19
			TOTAL SUBLET... 0.00
			TOTAL G.O.G.... 0.00
			TOTAL MISC.CHG. 51.12
			TOTAL MISC.DISC 0.00
			TOTAL TAX..... 0.00
			TOTAL INVOICE \$ 628.96

APPROVED BY SIGNATURE _____

THANK YOU

We are striving to keep you Completely Satisfied. You may soon receive a Service Survey.

	Outstanding
1. Was appointment available when requested?	9 10
2. Time waiting to speak to someone	0 10
3. Vehicle fixed right the first time	0 10
4. Service completed as promised	0 10
5. Service quality	0 10
6. Customer appreciation	0 10

If you cannot answer "Outstanding" (90% - 100%) please contact our Service Manager at (204) 275-4422. Below 90% reflects insufficient customer care in our opinion.

PAYMENT METHOD

MASTERCARD _____
VISA _____
DEBIT CARD _____
CASH _____
AMEX _____

Shop supplies' fees as shown on this invoice include necessary cleaners & degreasers, misc. clips, bolts, fasteners, connectors, lubricants, etc.

WARRANTY

Unless otherwise indicated, TOYOTA parts are warranted for 24 months or 40,000 kms, whichever comes first. Labour is covered if the part was installed by a TOYOTA dealer, TOYOTA parts, like batteries, mufflers, shock absorbers and struts, may have different coverage, shown on a label or other document provided to the customer.

Internet Service Appointment
www.CrownToyota.ca

ACCOUNTING COPY-I

[END OF INVOICE]

04:25pm

Work Order: R000001

VIN: 4T1BZ1FB1KU014381

Year: 19



Technician: 100632

Date: 5/10/21 4:09 PM



4T1BZ1FB1KU014381

Toyota 2019 Avalon Limited



• One or more values are not within specification. Tire wear, handling and safety problems may result.