



WAVERLEY AUTOMALL
 680 - 1717 WAVERLEY STREET
 WINNIPEG, MANITOBA R3T 6A9
 TEL: (204) 269-9686 (DIRECT)
 FAX: (204) 275-4432
 TOLL FREE: 1-866-823-3432
 EMAIL: service@CrownToyota.ca
 WEBSITE: www.CrownToyota.ca

TOIS371546

PRIVACY POLICY

Your privacy is a priority, we pledge continued respect and protection of your personal information. As a TOYOTA owner or lessee, this information is shared between us and Toyota Canada Inc. This allows us to provide ongoing communications that are relevant to you and your vehicle and which enhance your vehicle ownership. All personal information is maintained securely and from time to time may be supplied to third party agencies to ensure that we can serve your needs.

TOIS371546

GST #R8987 66 779



0201IT0IS371546

ALL ITEMS ARE SUBJECT TO G.S.T.

O
U
T

INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ _____ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS, & ACCESSORIES DESCRIBED IN THIS WORK ORDER.

DATE _____ SIGNATURE _____

CUSTOMER NO. 10	ADVISOR ALANA HIEBERT	40293	TAG NO. 6361	INVOICE DATE 04/28/21	INVOICE NO. TOIS371546
CROWN TOYOTA 680-1717 WAVERLEY STREET WINNIPEG, MB R3T 6A9	LABOUR RATE 139.95	LICENSE NO.	KILOMETERS 36,732	COLOUR WHITE/	STOCK NO. 2516361
	YEAR/MAKE/MODEL 19/SUBARU/OUTBACK/5DR WGN 2.5I TOUR			DELIVERY DATE	DELIVERY KMS. 36,732
	VEHICLE I.D. NO. 4 S 4 B S D D C 4 K 3 3 0 5 1 5 6			SELLING DEALER NO.	IN SERVICE DATE
finmgr1@crowntoyotascion.ca	F.T.E. NO. 898766779MT0003		P.O. NO.	R.O. DATE 04/27/21	
RESIDENCE PHONE	BUSINESS PHONE 204-269-1572	COMMENTS M0: 36732			

LABOR & PARTS-----
J# 1 69TOZZ02 GOVERNMENT SAFETY HOURS: 1.50 TECH(S):12282 189.95
 CONDITION: PERFORM MANITOBA PROVINCIAL SAFETY \$189.95
 REPAIR ITEMS MUST BE COMPLETED IN 30 DAYS
 (RE-INSPECTION CHARGE OF 19.95 APPLIES)
 CAUSE: SAFETY NUMBER 03164725
 CORRECTION: PERFORMED MB SAFETY INSPECTION

JOB # 1 TOTAL LABOR & PARTS 189.95

J# 2+01TOZ OIL CHANGE HOURS: TECH(S):12282 34.90
 CONDITION: REMOVE AND REPLACE ENGINE OIL & FILTER, INSPECT AIR FILTER,
 LUBRICATE LOCKS, LATCHES, AND HINGES, CHECK LIGHTS, HORN,
 AND WIPERS, CHECK COOLANT, BRAKE, WASHER FLUID LEVELS.
 CHECK AND ADJUST TIRE PRESSURES.
 4CYL & 6CYL (SYNTHETIC)...\$78.98...8CYL (SYNTH)...\$89.98
 CORRECTION: COMPLETED OIL AND FILTER SERVICE

PARTS-----QTY---FP-NUMBER-----DESCRIPTION-----UNIT PRICE-		
JOB # 2 1 361-2910 OIL FILTER	8.99	8.99
JOB # 2 5 COBBA-0W2SN-0B OW20 GF5	6.21	31.05
JOB # 2 TOTAL PARTS		40.04
JOB # 2 TOTAL LABOR & PARTS		74.94

J# 3+02TOZ ALIGNMENT HOURS: 1.00 TECH(S):100632 129.95
 CONDITION: FOUR WHEEL ALIGNMENT \$129.95
 CORRECTION: COMPLETE FOUR WHEEL ALIGNMENT

JOB # 3 TOTAL LABOR & PARTS 129.95

J# 4+18TOZZ12C 4WHEEL BRK SERVICE HOURS: TECH(S):12282 164.95
 CONDITION: CLEAN, LUBRICATE AND ADJUST BRAKES AND/OR EMERGENCY BRAKE
 SYSTEM, INSPECT CYLINDERS, HOSES AND LINES.
 REMOVE ALL HARDWARE AND CLIPS, GRIND CORROSION OFF
 ROTORS AND OR DRUMS, LUBRICATE AS NECESSARY,
 DEGLAZE REAR SHOES AND OR ALL PADS
 \$164.95
 CAUSE: CONSTANT EXPOSURE TO THE ELEMENTS MAY RESULT IN RUST
 BUILD-UP, WHICH CAN CAUSE BRAKE DRAGGING, PULLING, PULSATING,
 AND/OR ABNORMAL NOISE. REGULAR LUBRICATION AND CLEANING OF
 BRAKING SYSTEM COMPONENTS HELPS ENSURE PROPER FUNCTION
 AND REDUCE PREMATURE WEAR.
 CORRECTION: COMPLETED 4 WHEEL BRAKE SERVICE. LUBRICATED CALIPERS, SLIDERS
 AND PINS. DEGLAZE ROTORS AND DRUMS.

JOB # 4 TOTAL LABOR & PARTS 164.95

MISC-----CODE-----DESCRIPTION-----CONTROL NO-----		
JOB # A SSI SHOP SUPPLIES INTERNAL		51.12
TOTAL MISC		51.12

COMMENTS-----
 2516361

Internet Service Appointment
www.CrownToyota.ca

THANK YOU

We are striving
 to keep you
 Completely Satisfied.
 You may soon receive
 a Service Survey.

- Outstanding
- | | | | | |
|--|-----------------------|---|----------------------------------|----|
| 1. Was appointment available when requested? | <input type="radio"/> | 9 | <input checked="" type="radio"/> | 10 |
| 2. Time waiting to speak to someone | <input type="radio"/> | | <input checked="" type="radio"/> | |
| 3. Vehicle fixed right the first time | <input type="radio"/> | | <input checked="" type="radio"/> | |
| 4. Service completed as promised | <input type="radio"/> | | <input checked="" type="radio"/> | |
| 5. Service quality | <input type="radio"/> | | <input checked="" type="radio"/> | |
| 6. Customer appreciation | <input type="radio"/> | | <input checked="" type="radio"/> | |

If you cannot answer "Outstanding" (90% - 100%) please contact our Service Manager at (204) 275-4422. Below 90% reflects insufficient customer care in our opinion.

PAYMENT METHOD

MASTERCARD _____
 VISA _____
 DEBIT CARD _____
 CASH _____
 AMEX _____

Shop supplies' fees as shown on this invoice include necessary cleaners & degreasers, misc. clips, bolts, fasteners, connectors, lubricants, etc.

WARRANTY

Unless otherwise indicated, TOYOTA parts are warranted for 24 months or 40,000 kms, whichever comes first.
 Labour is covered if the part was installed by a TOYOTA dealer, TOYOTA parts, like batteries, mufflers, shock absorbers and struts, may have different coverage, shown on a label or other document provided to the customer.

TDG-CT-SRVINV



WAVERLEY AUTOMALL
 680 - 1717 WAVERLEY STREET
 WINNIPEG, MANITOBA R3T 6A9
 TEL: (204) 269-9686 (DIRECT)
 FAX: (204) 275-4432
 TOLL FREE: 1-866-823-3432
 EMAIL: service@CrownToyota.ca
 WEBSITE: www.CrownToyota.ca

TOIS371546

PRIVACY POLICY

Your privacy is a priority, we pledge continued respect and protection of your personal information. As a TOYOTA owner or lessee, this information is shared between us and Toyota Canada Inc. This allows us to provide ongoing communications that are relevant to you and your vehicle and which enhance your vehicle ownership. All personal information is maintained securely and from time to time may be supplied to third party agencies to ensure that we can serve your needs.

TOIS371546

GST #R8987 66 779



0201IT0IS371546

ALL ITEMS ARE SUBJECT TO G.S.T.

**O
U
T**

INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ _____ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS, & ACCESSORIES DESCRIBED IN THIS WORK ORDER.

DATE _____ SIGNATURE _____

CUSTOMER NO. 10	ADVISOR ALANA HIEBERT	40293	TAG NO. 6361	INVOICE DATE 04/28/21	INVOICE NO. TOIS371546
CROWN TOYOTA 680-1717 WAVERLEY STREET WINNIPEG, MB R3T 6A9	LABOUR RATE 139.95	LICENSE NO.	KILOMETERS 36,732	COLOUR WHITE/	STOCK NO. 2516361
	YEAR/MAKE/MODEL 19/SUBARU/OUTBACK/5DR WGN 2.5I TOUR			DELIVERY DATE	DELIVERY KMS. 36,732
	VEHICLE I.D. NO. 4 S 4 B S D D C 4 K 3 3 0 5 1 5 6			SELLING DEALER NO.	IN SERVICE DATE
	F.T.E. NO. 898766779MT0003	P.O. NO.	R.O. DATE 04/27/21		
RESIDENCE PHONE	BUSINESS PHONE 204-269-1572	COMMENTS MO: 36732			

TOTALS-----

CONTROL# 2516361	ACCOUNT NUMBER 1390	AMOUNT.. 610.91
---------------------	------------------------	--------------------

TOTAL LABOR....	519.75
TOTAL PARTS....	40.04
TOTAL SUBLET...	0.00
TOTAL G.O.G....	0.00
TOTAL MISC.CHG.	51.12
TOTAL MISC.DISC	0.00
TOTAL TAX.....	0.00

TOTAL INVOICE \$ 610.91

APPROVED BY SIGNATURE _____

THANK YOU

We are striving to keep you Completely Satisfied. You may soon receive a Service Survey.

- | | | |
|--|-----------------------|----------------------------------|
| | Outstanding | |
| 1. Was appointment available when requested? | 9 | 10 |
| 2. Time waiting to speak to someone | <input type="radio"/> | <input checked="" type="radio"/> |
| 3. Vehicle fixed right the first time | <input type="radio"/> | <input checked="" type="radio"/> |
| 4. Service completed as promised | <input type="radio"/> | <input checked="" type="radio"/> |
| 5. Service quality | <input type="radio"/> | <input checked="" type="radio"/> |
| 6. Customer appreciation | <input type="radio"/> | <input checked="" type="radio"/> |

If you cannot answer "Outstanding" (90% - 100%) please contact our Service Manager at (204) 275-4422. Below 90% reflects insufficient customer care in our opinion.

PAYMENT METHOD

- MASTERCARD _____
- VISA _____
- DEBIT CARD _____
- CASH _____
- AMEX _____

Shop supplies' fees as shown on this invoice include necessary cleaners & degreasers, misc. clips, bolts, fasteners, connectors, lubricants, etc.

WARRANTY

Unless otherwise indicated, TOYOTA parts are warranted for 24 months or 40,000 kms, whichever comes first. Labour is covered if the part was installed by a TOYOTA dealer, TOYOTA parts, like batteries, mufflers, shock absorbers and struts, may have different coverage, shown on a label or other document provided to the customer.

Internet Service Appointment
www.CrownToyota.ca



ACCOUNTING COPY-I

[END OF INVOICE]

11:38am



Subaru 2018-19 Outback



• One or more values are not within specification. Tire wear, handling and safety problems may result.