



WAVERLEY AUTOMALL
 680 - 1717 WAVERLEY STREET
 WINNIPEG, MANITOBA R3T 6A9
 TEL: (204) 269-9686 (DIRECT)
 FAX: (204) 275-4432
 TOLL FREE: 1-866-823-3432
 EMAIL: service@CrownToyota.ca
 WEBSITE: www.CrownToyota.ca

GST #R8987 66 779

TOIS362258

PRIVACY POLICY

Your privacy is a priority, we pledge continued respect and protection of your personal information. As a TOYOTA owner or lessee, this information is shared between us and Toyota Canada Inc. This allows us to provide ongoing communications that are relevant to you and your vehicle and which enhance your vehicle ownership. All personal information is maintained securely and from time to time may be supplied to third party agencies to ensure that we can serve your needs

TOIS362258



02011TOIS362258

ALL ITEMS ARE SUBJECT TO G.S.T.

O U T INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ _____ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS, & ACCESSORIES DESCRIBED IN THIS WORK ORDER.
 DATE _____ SIGNATURE _____

CUSTOMER NO. 10	ADVISOR ALANA HIEBERT	40293	TAG NO. 9611	INVOICE DATE 10/06/20	INVOICE NO. TOIS362258
CROWN TOYOTA 680-1717 WAVERLEY STREET WINNIPEG, MB R3T 6A9	LABOUR RATE 139.95	LICENSE NO. KBP607	KILOMETERS 7,386	COLOUR AQUA/	STOCK NO. 2509611
	YEAR/MAKE/MODEL 18/TOYOTA/COROLLA/CERT LE			DELIVERY DATE 09/26/18	DELIVERY KMS 7,386
	VEHICLE I.D. NO. 2 T 1 B U R H E 6 J C O 9 0 8 5 9			SELLING DEALER NO. 34027	IN SERVICE DATE 04/04/18
	F.T.E. NO.	P.O. NO.	B.O. DATE 09/30/20	09/26/18	
finmgr1@crowntoyotascion.ca	COMMENTS E# ZRE172L-DEXNKK			MO: 7388 REPRINT# 1	
RESIDENCE PHONE	BUSINESS PHONE 204-269-1572				

LABOR & PARTS	DESCRIPTION	HOURS	TECH(S)	PRICE
J# 1 69TOZZ02	GOVERNMENT SAFETY	1.50	68812	189.95
CONDITION: PERFORM MANITOBA PROVINCIAL SAFETY \$189.95 REPAIR ITEMS MUST BE COMPLETED IN 30 DAYS (RE-INSPECTION CHARGE OF 19.95 APPLIES)				
CAUSE: SAFETY NUMBER 03089667				
CORRECTION: PERFORMED MB SAFETY INSPECTION				
JOB # 1 TOTAL LABOR & PARTS				189.95
J# 2 69TOZZ01	T.C.U.V. CERTIFIED	1.00	68812	125.00
CONDITION: PERFORM TCUV INSPECTION. COMPLETE FORM. PROVIDE PAPERWORK TO SERVICE MANAGER				
CAUSE: J 79524				
CORRECTION: COMPLETED TCUV INSPECTION				
JOB # 2 TOTAL LABOR & PARTS				125.00
J# 3+18TOZZ10	ROTORS (FRONT)		68812	139.95
CONDITION: REMOVE AND REPLACE FRONT ROTORS- EXCESSIVE RUST BUILD UP				
CORRECTION: REPLACED ROTORS				
PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE
JOB # 3	2	43512-02240	ROTOR, BRAKE FRON	89.95
JOB # 3 TOTAL PARTS				179.90
JOB # 3 TOTAL LABOR & PARTS				319.85
J# 4+01TOZ	OIL CHANGE		68812	20.71
CONDITION: REMOVE AND REPLACE ENGINE OIL & FILTER, INSPECT AIR FILTER, LUBRICATE LOCKS, LATCHES, AND HINGES, CHECK LIGHTS, HORN, AND WIPERS, CHECK COOLANT, BRAKE, WASHER FLUID LEVELS. CHECK AND ADJUST TIRE PRESSURES.				
CORRECTION: COMPLETED OIL AND FILTER SERVICE				
PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE
JOB # 4	1	PKYZZF2-0W20	OIL CHANGE	36.24
JOB # 4	1	90430-12028	GASKET	****
JOB # 4	1	90915-YZZF2	FILTER S/A, OIL	****
JOB # 4	5	COBBA-0W2SN-0B	0W20 GF5	****
JOB # 4 TOTAL PARTS				36.24
JOB # 4 TOTAL LABOR & PARTS				56.95
J# 5+09TOZCABIN	CABIN FILTER		68812	20.04
CONDITION: AFTER INSPECTION, CABIN FILTER NEEDS REPLACEMENT. INSTALL PRICE \$69.95 PLUS TAXES AND FEES.				
CAUSE: CABIN FILTER FOUND TO BE PLUGGED WITH DIRT AND DUST.				
CORRECTION: REMOVE OLD CABIN FILTER, NEW CABIN FILTER INSTALLED.				
PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE
JOB # 5	1	87139-YZZ20	ELEMENT AIR REPT	32.95

THANK YOU

We are striving to keep you Completely Satisfied. You may soon receive a Service Survey.

	Outstanding
1. Was appointment available when requested?	9 <input type="radio"/> 10 <input checked="" type="radio"/>
2. Time waiting to speak to someone	<input type="radio"/> <input checked="" type="radio"/>
3. Vehicle fixed right the first time	<input type="radio"/> <input checked="" type="radio"/>
4. Service completed as promised	<input type="radio"/> <input checked="" type="radio"/>
5. Service quality	<input type="radio"/> <input checked="" type="radio"/>
6. Customer appreciation	<input type="radio"/> <input checked="" type="radio"/>

If you cannot answer "Outstanding" (90% - 100%) please contact our Service Manager at (204) 275-4422. Below 90% reflects insufficient customer care in our opinion.

PAYMENT METHOD

MASTERCARD _____
 VISA _____
 DEBIT CARD _____
 CASH _____
 AMEX _____

Shop supplies' fees as shown on this invoice include necessary cleaners & degreasers, misc. clips, bolts, fasteners, connectors, lubricants, etc.

WARRANTY

Unless otherwise indicated, TOYOTA parts are warranted for 24 months or 40,000 kms, whichever comes first. Labour is covered if the part was installed by a TOYOTA dealer, TOYOTA parts, like batteries, mufflers, shock absorbers and struts, may have different coverage, shown on a label or other document provided to the customer.

Internet Service Appointment
www.CrownToyota.ca

ACCOUNTING COPY-I

[CONTINUED ON NEXT PAGE]

10:20am

TDG-CT-SRVINV



WAVERLEY AUTOMALL
 680 - 1717 WAVERLEY STREET
 WINNIPEG, MANITOBA R3T 6A9
 TEL: (204) 269-9686 (DIRECT)
 FAX: (204) 275-4432
 TOLL FREE: 1-866-823-3432
 EMAIL: service@CrownToyota.ca
 WEBSITE: www.CrownToyota.ca

GST #R8987 66 779

TOIS362258

PRIVACY POLICY

Your privacy is a priority, we pledge continued respect and protection of your personal information. As a TOYOTA owner or lessee, this information is shared between us and Toyota Canada Inc. This allows us to provide ongoing communications that are relevant to you and your vehicle and which enhance your vehicle ownership. All personal information is maintained securely and from time to time may be supplied to third party agencies to ensure that we can serve your needs

TOIS362258



0201ITOIS362258

ALL ITEMS ARE SUBJECT TO G.S.T.

**O
U
T**

INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ _____ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS, & ACCESSORIES DESCRIBED IN THIS WORK ORDER.

DATE _____ SIGNATURE _____

CUSTOMER NO. 10	ADVISOR ALANA HIEBERT	40293	TAG NO. 9611	INVOICE DATE 10/06/20	INVOICE NO. TOIS362258
CROWN TOYOTA 680-1717 WAVERLEY STREET WINNIPEG, MB R3T 6A9	LABOUR RATE 139.95	LICENSE NO. KBP607	KILOMETERS 7,386	COLOUR AQUA/	STOCK NO. 2509611
	YEAR/MAKE/MODEL 18/TOYOTA/COROLLA/CERT LE			DELIVERY DATE 09/26/18	DELIVERY KMS. 7,386
	VEHICLE I.D. NO. 2 T 1 B U R H E 6 J C O 9 0 8 5 9			SELLING DEALER NO. 34027	IN SERVICE DATE 04/04/18
	FILE NO.	PO. NO.		R.O. DATE 09/30/20	09/26/18
finmgr1@crowntoyotascion.ca	RESIDENCE PHONE	BUSINESS PHONE 204-269-1572	COMMENTS E# ZRE172L-DEXNKK	M0: 7388 REPRINT# 1	

JOB # 5 TOTAL PARTS		32.95
JOB # 5 TOTAL LABOR & PARTS		52.99
J# 6+09TOZZ17A	WIPER BLADES	HOURS: TECH(S):68812
CONDITION: REMOVE AND REPLACE THE WIPERS		
CORRECTION: INSTALLED WIPER BLADES		
PARTS-----QTY-----FP-NUMBER-----	DESCRIPTION-----	UNIT PRICE-
JOB # 6 1 C0222-WTR16	BLADE,WIPER	18.50
JOB # 6 1 C0222-WTR26	BLADE,WIPER	18.50
JOB # 6 TOTAL PARTS		37.00
JOB # 6 TOTAL LABOR & PARTS		37.00
J# 7+02TOZ	ALIGNMENT	HOURS: TECH(S):58601
CONDITION: FOUR WHEEL ALIGNMENT \$129.95		
CORRECTION: COMPLETED ALIGNMENT CHECK		
JOB # 7 TOTAL LABOR & PARTS		39.95
MISC-----CODE-----DESCRIPTION-----	CONTROL NO-----	
JOB # A SSI SHOP SUPPLIES INTERNAL		51.12
TOTAL - MISC		51.12
COMMENTS-----		
2509611		
TOTALS-----		
CONTROL#	ACCOUNT NUMBER	AMOUNT..
2509611	1390	872.81
TOTAL LABOR....		535.60
TOTAL PARTS....		286.09
TOTAL SUBLET...		0.00
TOTAL G.O.G....		0.00
TOTAL MISC.CHG.		51.12
TOTAL MISC.DISC		0.00
TOTAL TAX.....		0.00
TOTAL INVOICE \$		872.81

THANK YOU

We are striving to keep you Completely Satisfied. You may soon receive a Service Survey.

	Outstanding
1. Was appointment available when requested?	9 10
2. Time waiting to speak to someone	0 10
3. Vehicle fixed right the first time	0 10
4. Service completed as promised	0 10
5. Service quality	0 10
6. Customer appreciation	0 10

If you cannot answer "Outstanding" (90% - 100%) please contact our Service Manager at (204) 275-4422. Below 90% reflects insufficient customer care in our opinion.

PAYMENT METHOD

MASTERCARD _____
VISA _____
DEBIT CARD _____
CASH _____
AMEX _____

Shop supplies' fees as shown on this invoice include necessary cleaners & degreasers, misc. clips, bolts, fasteners, connectors, lubricants, etc.

WARRANTY

Unless otherwise indicated, TOYOTA parts are warranted for 24 months or 40,000 kms, whichever comes first. Labour is covered if the part was installed by a TOYOTA dealer, TOYOTA parts, like batteries, mufflers, shock absorbers and struts, may have different coverage, shown on a label or other document provided to the customer.

Internet Service Appointment
www.CrownToyota.ca

ACCOUNTING COPY-I

[END OF INVOICE] 10:20am