



WAVERLEY AUTOMALL
 680 - 1717 WAVERLEY STREET
 WINNIPEG, MANITOBA R3T 6A9
 TEL: (204) 269-9686 (DIRECT)
 FAX: (204) 275-4432
 TOLL FREE: 1-866-823-3432
 EMAIL: service@CrownToyota.ca
 WEBSITE: www.CrownToyota.ca

TOIS365734

PRIVACY POLICY

Your privacy is a priority, we pledge continued respect and protection of your personal information. As a TOYOTA owner or lessee, this information is shared between us and Toyota Canada Inc. This allows us to provide ongoing communications that are relevant to you and your vehicle and which enhance your vehicle ownership. All personal information is maintained securely and from time to time may be supplied to third party agencies to ensure that we can serve your needs.

TOIS365734

GST #R8987 66 779



0201IT0IS365734

ALL ITEMS ARE SUBJECT TO G.S.T.

OUT

INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ _____ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS, & ACCESSORIES DESCRIBED IN THIS WORK ORDER.

DATE _____ SIGNATURE _____

CUSTOMER NO. 10	ADVISOR ALANA HIEBERT	40293	TAG NO. 2381	INVOICE DATE 12/14/20	INVOICE NO. TOIS365734
CROWN TOYOTA 680-1717 WAVERLEY STREET WINNIPEG, MB R3T 6A9	LABOUR RATE 139.95	LICENSE NO.	KILOMETERS 10,409	COLOUR BLACK/	STOCK NO. 2602381
	YEAR/MAKE/MODEL 20/TOYOTA/COROLLA/SE PWLM CC AC KE C			DELIVERY DATE	DELIVERY KMS. 10,409
	VEHICLE I.D. NO. 5 Y F B 4 R B E 2 L P 0 0 1 7 6 7			SELLING DEALER NO. 14075	IN SERVICE DATE 03/21/19
finmgr1@crowntoyotascion.ca	F.T.E. NO.		P.O. NO.	R.O. DATE 12/14/20	10/18/19
RESIDENCE PHONE	BUSINESS PHONE 204-269-1572	COMMENTS E# MZEA12L -DEXSBK		MO: 10409	

LABOR & PARTS-----
J# 1 TOZZ HOURS: TECH(S):999 0.00
 CONDITION: COMPLETE OUTSTANDING RECALL RB3 -
 CAUSE: RECALL HASNT BEEN RELEASED
 CORRECTION: RECALL NOT COMPLETED

JOB # 1 TOTAL LABOR & PARTS 0.00

J# 2 69TOZZ02 GOVERNMENT SAFETY HOURS: 1.50 TECH(S):68812 189.95
 CONDITION: PERFORM MANITOBA PROVINCIAL SAFETY \$189.95
 REPAIR ITEMS MUST BE COMPLETED IN 30 DAYS
 (RE-INSPECTION CHARGE OF 19.95 APPLIES)
 CAUSE: SAFETY 03109357
 CORRECTION: PERFORMED MB SAFETY INSPECTION

JOB # 2 TOTAL LABOR & PARTS 189.95

J# 3 69TOZZ01 T.C.U.V. CERTIFIED HOURS: 1.00 TECH(S):68812 125.00
 CONDITION: PERFORM TCUV INSPECTION.
 COMPLETE FORM.
 PROVIDE PAPERWORK TO SERVICE MANAGER
 CAUSE: J 79686
 CORRECTION: COMPLETED TCUV INSPECTION

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	PRICE
JOB # 3	1	87139-0R030	ELEMENT, AIR REFI	32.95	32.95
JOB # 3 TOTAL PARTS					32.95
JOB # 3 TOTAL LABOR & PARTS					157.95

J# 4+09TOZCABIN CABIN FILTER HOURS: TECH(S):68812 20.04
 CONDITION: AFTER INSPECTION, CABIN FILTER NEEDS REPLACEMENT.
 INSTALL PRICE \$69.95 PLUS TAXES AND FEES.
 CAUSE: CABIN FILTER FOUND TO BE PLUGGED WITH DIRT AND DUST.
 CORRECTION: REMOVE OLD CABIN FILTER, NEW CABIN FILTER INSTALLED.

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	PRICE
JOB # 4	1	C0222-WTR26	BLADE,WIPER	18.50	18.50
JOB # 4	1	C0222-WTR16	BLADE,WIPER	18.50	18.50
JOB # 4 TOTAL PARTS					37.00
JOB # 4 TOTAL LABOR & PARTS					57.04

J# 5+09TOZZ17A WIPER BLADES HOURS: TECH(S):68812 0.00
 CONDITION: REMOVE AND REPLACE WIPER BLADES
 CORRECTION: INSTALLED WIPER BLADES

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	PRICE
JOB # 5	1	PKYZZF2-0W20	OIL CHANGE	36.24	36.24
JOB # 5	1	90430-12028	GASKET	****	****
JOB # 5	1	90915-YZZN1	FILTER S/A, OIL	****	****
JOB # 5	5	COBBA-0W2SN-0B	0W20 GF5	****	****
JOB # 5 TOTAL PARTS					36.24

THANK YOU

We are striving to keep you Completely Satisfied. You may soon receive a Service Survey.

	9	10
1. Was appointment available when requested?	<input type="radio"/>	<input checked="" type="radio"/>
2. Time waiting to speak to someone	<input type="radio"/>	<input checked="" type="radio"/>
3. Vehicle fixed right the first time	<input type="radio"/>	<input checked="" type="radio"/>
4. Service completed as promised	<input type="radio"/>	<input checked="" type="radio"/>
5. Service quality	<input type="radio"/>	<input checked="" type="radio"/>
6. Customer appreciation	<input type="radio"/>	<input checked="" type="radio"/>

If you cannot answer "Outstanding" (90% - 100%) please contact our Service Manager at (204) 275-4422. Below 90% reflects insufficient customer care in our opinion.

PAYMENT METHOD

MASTERCARD _____
 VISA _____
 DEBIT CARD _____
 CASH _____
 AMEX _____

Shop supplies' fees as shown on this invoice include necessary cleaners & degreasers, misc. clips, bolts, fasteners, connectors, lubricants, etc.

WARRANTY

Unless otherwise indicated, TOYOTA parts are warranted for 24 months or 40,000 kms, whichever comes first. Labour is covered if the part was installed by a TOYOTA dealer, TOYOTA parts, like batteries, mufflers, shock absorbers and struts, may have different coverage, shown on a label or other document provided to the customer.

Internet Service Appointment
www.CrownToyota.ca

ACCOUNTING COPY-I

[CONTINUED ON NEXT PAGE]

03:42pm

TDG-CT-SRVINV



WAVERLEY AUTOMALL
 680 - 1717 WAVERLEY STREET
 WINNIPEG, MANITOBA R3T 6A9
 TEL: (204) 269-9686 (DIRECT)
 FAX: (204) 275-4432
 TOLL FREE: 1-866-823-3432
 EMAIL: service@CrownToyota.ca
 WEBSITE: www.CrownToyota.ca

TOIS365734

PRIVACY POLICY

Your privacy is a priority, we pledge continued respect and protection of your personal information. As a TOYOTA owner or lessee, this information is shared between us and Toyota Canada Inc. This allows us to provide ongoing communications that are relevant to you and your vehicle and which enhance your vehicle ownership. All personal information is maintained securely and from time to time may be supplied to third party agencies to ensure that we can serve your needs.

TOIS365734

GST #R8987 66 779



0201IT0IS365734

ALL ITEMS ARE SUBJECT TO G.S.T.

OUT

INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ _____ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS, & ACCESSORIES DESCRIBED IN THIS WORK ORDER.

DATE _____ SIGNATURE _____

CUSTOMER NO. 10	ADVISOR ALANA HIEBERT	40293	TAG NO. 2381	INVOICE DATE 12/14/20	INVOICE NO. TOIS365734
CROWN TOYOTA 680-1717 WAVERLEY STREET WINNIPEG, MB R3T 6A9	LABOUR RATE 139.95	LICENSE NO.	KILOMETERS 10,409	COLOUR BLACK/	STOCK NO. 2602381
	YEAR/MAKE/MODEL 20/TOYOTA/COROLLA/SE PWLM CC AC KE C			DELIVERY DATE	DELIVERY KMS. 10,409
	VEHICLE I.D. NO. 5 Y F B 4 R B E 2 L P 0 0 1 7 6 7			SELLING DEALER NO. 14075	IN SERVICE DATE 03/21/19
	F.T.E. NO.		P.O. NO.	R.O. DATE 12/14/20	10/18/19
finmgr1@crowntoyotascion.ca	COMMENTS E# MZEA12L -DEXSBK				
RESIDENCE PHONE	BUSINESS PHONE 204-269-1572				

JOB # 5 TOTAL LABOR & PARTS		36.24
J# 6+01TOZ	OIL CHANGE	HOURS: TECH(S):68812
CONDITION:	REMOVE AND REPLACE ENGINE OIL & FILTER, INSPECT AIR FILTER, LUBRICATE LOCKS, LATCHES, AND HINGES, CHECK LIGHTS, HORN, AND WIPERS, CHECK COOLANT, BRAKE, WASHER FLUID LEVELS. CHECK AND ADJUST TIRE PRESSURES. 4CYL & 6CYL (SYNTHETIC)...\$78.98...8CYL (SYNTH)...\$89.98	
CORRECTION:	COMPLETED OIL AND FILTER SERVICE	
JOB # 6 TOTAL LABOR & PARTS		20.71
J# 7+02TOZ	ALIGNMENT	HOURS: 1.00 TECH(S):100632
CONDITION:	FOUR WHEEL ALIGNMENT \$129.95	
CORRECTION:	COMPLETED FOUR WHEEL ALIGNMENT	
JOB # 7 TOTAL LABOR & PARTS		129.95
MISC-----CODE-----DESCRIPTION-----CONTROL NO-----		
JOB # A	SSI SHOP SUPPLIES INTERNAL	51.12
	TOTAL - MISC	51.12
COMMENTS-----		
2602381		
TOTALS-----		
CONTROL#	ACCOUNT NUMBER	AMOUNT..
2602381	1390	642.96
	TOTAL LABOR....	485.65
	TOTAL PARTS....	106.19
	TOTAL SUBLET...	0.00
	TOTAL G.O.G....	0.00
	TOTAL MISC.CHG.	51.12
	TOTAL MISC.DISC	0.00
	TOTAL TAX.....	0.00
	TOTAL INVOICE \$	642.96

MO: 10409

THANK YOU

We are striving to keep you Completely Satisfied. You may soon receive a Service Survey.

	Outstanding
1. Was appointment available when requested?	9 10
2. Time waiting to speak to someone	0 10
3. Vehicle fixed right the first time	0 10
4. Service completed as promised	0 10
5. Service quality	0 10
6. Customer appreciation	0 10

If you cannot answer "Outstanding" (90% - 100%) please contact our Service Manager at (204) 275-4422. Below 90% reflects insufficient customer care in our opinion.

PAYMENT METHOD

MASTERCARD _____
 VISA _____
 DEBIT CARD _____
 CASH _____
 AMEX _____

Shop supplies' fees as shown on this invoice include necessary cleaners & degreasers, misc. clips, bolts, fasteners, connectors, lubricants, etc.

WARRANTY
 Unless otherwise indicated, TOYOTA parts are warranted for 24 months or 40,000 kms, whichever comes first. Labour is covered if the part was installed by a TOYOTA dealer, TOYOTA parts, like batteries, mufflers, shock absorbers and struts, may have different coverage, shown on a label or other document provided to the customer.

Internet Service Appointment
 www.CrownToyota.ca

ACCOUNTING COPY-I

[END OF INVOICE]

03:42pm

TDG-CT-SRVINV