



WAVERLEY AUTOMALL
 680 - 1717 WAVERLEY STREET
 WINNIPEG, MANITOBA R3T 6A9
 TEL: (204) 269-9686 (DIRECT)
 FAX: (204) 275-4432
 TOLL FREE: 1-866-823-3432
 EMAIL: service@CrownToyota.ca
 WEBSITE: www.CrownToyota.ca

TOIS365777

PRIVACY POLICY

Your privacy is a priority, we pledge continued respect and protection of your personal information. As a TOYOTA owner or lessee, this information is shared between us and Toyota Canada Inc. This allows us to provide ongoing communications that are relevant to you and your vehicle and which enhance your vehicle ownership. All personal information is maintained securely and from time to time may be supplied to third party agencies to ensure that we can serve your needs.

TOIS365777

GST #R8987 66 779



0201IT0IS365777

ALL ITEMS ARE SUBJECT TO G.S.T.

OUT

INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ _____ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS, & ACCESSORIES DESCRIBED IN THIS WORK ORDER.
 DATE _____ SIGNATURE _____

CUSTOMER NO. 10	ADVISOR ALANA HIEBERT	40293	TAG NO. 4822	INVOICE DATE 12/15/20	INVOICE NO. TOIS365777
CROWN TOYOTA 680-1717 WAVERLEY STREET WINNIPEG, MB R3T 6A9 finmgr1@crowntoyotascion.ca	LABOUR RATE 139.95	LICENSE NO. HYZ996	KILOMETERS 28,318	COLOUR BLACK/	STOCK NO. 94822
	YEAR/MAKE/MODEL 18/TOYOTA/COROLLA/SE 4DR PWLM SR AC	DELIVERY DATE 05/08/18		DELIVERY KMS 28,318	
	VEHICLE I.D. NO. 2 T 1 B U R H E 1 J C 0 9 6 1 3 3	SELLING DEALER NO. 34027		IN SERVICE DATE 04/12/18	
	F.T.E. NO. _____	PO. NO. _____	R.O. DATE 12/15/20	05/08/18	
RESIDENCE PHONE _____	BUSINESS PHONE 204-269-1572	COMMENTS E# ZRE172L-DEXSKK			MO: 28321

LABOR & PARTS-----
J# 3 69TOZZ02 GOVERNMENT SAFETY HOURS: 1.50 TECH(S):68812 189.95
 CONDITION: PERFORM MANITOBA PROVINCIAL SAFETY \$189.95
 REPAIR ITEMS MUST BE COMPLETED IN 30 DAYS
 (RE-INSPECTION CHARGE OF 19.95 APPLIES)
 CAUSE: SAFETY NUMBER 03109358
 CORRECTION: PERFORMED MB SAFETY INSPECTION
 JOB # 3 TOTAL LABOR & PARTS 189.95

J# 4 69TOZZ01 T.C.U.V. CERTIFIED HOURS: 1.00 TECH(S):68812 125.00
 CONDITION: PERFORM TCUV INSPECTION.
 COMPLETE FORM.
 PROVIDE PAPERWORK TO SERVICE MANAGER
 CAUSE: J 79687
 CORRECTION: COMPLETED TCUV INSPECTION
 JOB # 4 TOTAL LABOR & PARTS 125.00

J# 5+18TOZZ10 ROTORS (FRONT) HOURS: TECH(S):68812 139.95
 CONDITION: REMOVE AND REPLACE THE FRONT ROTORS
 CORRECTION: REPLACED FRONT ROTORS AND SERVICED CALIPER
 PARTS-----QTY---FP-NUMBER-----DESCRIPTION-----UNIT PRICE-
 JOB # 5 2 43512-02240 ROTOR, BRAKE FRON 89.95 179.90
 JOB # 5 TOTAL PARTS 179.90
 JOB # 5 TOTAL LABOR & PARTS 319.85

J# 6+01TOZ OIL CHANGE HOURS: TECH(S):68812 20.71
 CONDITION: REMOVE AND REPLACE ENGINE OIL & FILTER, INSPECT AIR FILTER,
 LUBRICATE LOCKS, LATCHES, AND HINGES, CHECK LIGHTS, HORN,
 AND WIPERS, CHECK COOLANT, BRAKE, WASHER FLUID LEVELS.
 CHECK AND ADJUST TIRE PRESSURES.
 4CYL & 6CYL (SYNTHETIC)...\$78.98...8CYL (SYNTH)...\$89.98
 CORRECTION: COMPLETED OIL AND FILTER SERVICE
 PARTS-----QTY---FP-NUMBER-----DESCRIPTION-----UNIT PRICE-
 JOB # 6 1 PKYZZF2-0W20 OIL CHANGE 36.24
 JOB # 6 1 90430-12028 GASKET ****
 JOB # 6 1 90915-YZZN1 FILTER S/A, OIL ****
 JOB # 6 5 COBBA-0W25N-0B OW20 GFS ****
 JOB # 6 TOTAL PARTS 36.24
 JOB # 6 TOTAL LABOR & PARTS 56.95

J# 7+02TOZ ALIGNMENT HOURS: 1.00 TECH(S):100632 129.95
 CONDITION: FOUR WHEEL ALIGNMENT \$129.95
 CORRECTION: COMPLETED 4 WHEEL ALIGNMENT
 JOB # 7 TOTAL LABOR & PARTS 129.95

J# 8+09TOZ QUICK SERVICE HOURS: TECH(S):68812 20.04
 CONDITION: REMOVE AND REPLACE THE CABIN FILTER
 CAUSE: DIRTY

THANK YOU

We are striving
 to keep you
 Completely Satisfied.
 You may soon receive
 a Service Survey.

- Outstanding
- Was appointment available when requested? 9 10
 - Time waiting to speak to someone
 - Vehicle fixed right the first time
 - Service completed as promised
 - Service quality
 - Customer appreciation

If you cannot answer "Outstanding" (90% - 100%) please contact our Service Manager at (204) 275-4422. Below 90% reflects insufficient customer care in our opinion.

PAYMENT METHOD

- MASTERCARD _____
 VISA _____
 DEBIT CARD _____
 CASH _____
 AMEX _____

Shop supplies' fees as shown on this invoice include necessary cleaners & degreasers, misc. clips, bolts, fasteners, connectors, lubricants, etc.

WARRANTY

Unless otherwise indicated, TOYOTA parts are warranted for 24 months or 40,000 kms, whichever comes first.
 Labour is covered if the part was installed by a TOYOTA dealer, TOYOTA parts, like batteries, mufflers, shock absorbers and struts, may have different coverage, shown on a label or other document provided to the customer.

Internet Service Appointment
www.CrownToyota.ca

TDG-CT-SRVINV



WAVERLEY AUTOMALL
 680 - 1717 WAVERLEY STREET
 WINNIPEG, MANITOBA R3T 6A9
 TEL: (204) 269-9686 (DIRECT)
 FAX: (204) 275-4432
 TOLL FREE: 1-866-823-3432
 EMAIL: service@CrownToyota.ca
 WEBSITE: www.CrownToyota.ca

TOIS365777

PRIVACY POLICY

Your privacy is a priority, we pledge continued respect and protection of your personal information. As a TOYOTA owner or lessee, this information is shared between us and Toyota Canada Inc. This allows us to provide ongoing communications that are relevant to you and your vehicle and which enhance your vehicle ownership. All personal information is maintained securely and from time to time may be supplied to third party agencies to ensure that we can serve your needs.

TOIS365777

GST #R8987 66 779



0201IT0IS365777

ALL ITEMS ARE SUBJECT TO G.S.T.

OUT

INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ _____ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS, & ACCESSORIES DESCRIBED IN THIS WORK ORDER.

DATE _____ SIGNATURE _____

CUSTOMER NO. 10	ADVISOR ALANA HIEBERT	40293	TAG NO. 4822	INVOICE DATE 12/15/20	INVOICE NO. TOIS365777
CROWN TOYOTA 680-1717 WAVERLEY STREET WINNIPEG, MB R3T 6A9	LABOUR RATE 139.95	LICENSE NO. HYZ996	KILOMETERS 28,318	COLOUR BLACK/	STOCK NO. 94822
finmgr1@crowntoyotascion.ca	YEAR/MAKE/MODEL 18/TOYOTA/COROLLA/SE 4DR PWLM SR AC	DELIVERY DATE 05/08/18	DELIVERY KMS. 28,318	VEHICLE I.D. NO. 2 T 1 B U R H E 1 J C 0 9 6 1 3 3	SELLING DEALER NO. 34027
RESIDENCE PHONE	BUSINESS PHONE 204-269-1572	COMMENTS E# ZRE172L-DEXSKK	PO. NO.	R.O. DATE 12/15/20	IN SERVICE DATE 04/12/18
			MO: 28321		

CORRECTION: REPLACED FILTER

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	PRICE
JOB # 8	1	17801-YZZ05	ELEMENT SUB-ASSEM	19.95	19.95
				JOB # 8 TOTAL PARTS	19.95
				JOB # 8 TOTAL LABOR & PARTS	39.99

J# 9+09TOZZ-AF AIR FILTER HOURS: TECH(S):68812 20.04

CONDITION: REPLACE THE ENGINE AIR FILTER
 CORRECTION: REPLACED AIR FILTER.

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	PRICE
JOB # 9	1	87139-YZZ20	ELEMENT, AIR REFI	32.95	32.95
				JOB # 9 TOTAL PARTS	32.95
				JOB # 9 TOTAL LABOR & PARTS	52.99

J#10+09TOZZ17A WIPER BLADES HOURS: TECH(S):68812 0.00

CONDITION: INSTALL WIPER BLADES
 CORRECTION: INSTALLED WIPER BLADES

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	PRICE
JOB # 10	1	C0222-WTR26	BLADE,WIPER	18.50	18.50
JOB # 10	1	C0222-WTR16	BLADE,WIPER	18.50	18.50
				JOB # 10 TOTAL PARTS	37.00
				JOB # 10 TOTAL LABOR & PARTS	37.00

J#11+18TOZZ11 REAR BRAKE SERVICE HOURS: TECH(S):68812 84.95

CONDITION: PERFORM REAR BRAKE SERVICE
 -DEGLAZE REAR SHOES
 -CLEAN CORROSION FROM REAR DRUMS
 -LUBRICATE THE ADJUSTERS SLIDERS
 \$84.95
 CORRECTION: PERFORMED REAR BRAKE SERVICE

JOB # 11 TOTAL LABOR & PARTS 84.95

J#12+18TOZZ01 BRAKE FLUID FLUSH HOURS: TECH(S):68812 122.03

CONDITION: POWER VACUUM AND BLEED HYDRAULIC SYSTEM AND REPLACE WITH GENUINE TOYOTA BRAKE FLUID.INSPECT HYDRAULIC LINES AND HOSES
 \$109.95
 CORRECTION: COMPLETED BRAKE FLUID FLUSH

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	PRICE
JOB # 12	1	C0009-00127	DOT 3 BRAKE FLUID	7.16	7.16
				JOB # 12 TOTAL PARTS	7.16
				JOB # 12 TOTAL LABOR & PARTS	129.19

MISC	CODE	DESCRIPTION	CONTROL NO	PRICE
JOB # A	SSI	SHOP SUPPLIES INTERNAL		51.12

THANK YOU

We are striving to keep you Completely Satisfied. You may soon receive a Service Survey.

	9	10
1. Was appointment available when requested?	<input type="radio"/>	<input checked="" type="radio"/>
2. Time waiting to speak to someone	<input type="radio"/>	<input checked="" type="radio"/>
3. Vehicle fixed right the first time	<input type="radio"/>	<input checked="" type="radio"/>
4. Service completed as promised	<input type="radio"/>	<input checked="" type="radio"/>
5. Service quality	<input type="radio"/>	<input checked="" type="radio"/>
6. Customer appreciation	<input type="radio"/>	<input checked="" type="radio"/>

If you cannot answer "Outstanding" (90% - 100%) please contact our Service Manager at (204) 275-4422. Below 90% reflects insufficient customer care in our opinion.

PAYMENT METHOD

MASTERCARD _____
 VISA _____
 DEBIT CARD _____
 CASH _____
 AMEX _____

Shop supplies' fees as shown on this invoice include necessary cleaners & degreasers, misc. clips, bolts, fasteners, connectors, lubricants, etc.

WARRANTY

Unless otherwise indicated, TOYOTA parts are warranted for 24 months or 40,000 kms, whichever comes first. Labour is covered if the part was installed by a TOYOTA dealer, TOYOTA parts, like batteries, mufflers, shock absorbers and struts, may have different coverage, shown on a label or other document provided to the customer.

TDG-CT-SRVINV

Internet Service Appointment
www.CrownToyota.ca



WAVERLEY AUTOMALL
 680 - 1717 WAVERLEY STREET
 WINNIPEG, MANITOBA R3T 6A9
 TEL: (204) 269-9686 (DIRECT)
 FAX: (204) 275-4432
 TOLL FREE: 1-866-823-3432
 EMAIL: service@CrownToyota.ca
 WEBSITE: www.CrownToyota.ca

TOIS365777

PRIVACY POLICY

Your privacy is a priority, we pledge continued respect and protection of your personal information. As a TOYOTA owner or lessee, this information is shared between us and Toyota Canada Inc. This allows us to provide ongoing communications that are relevant to you and your vehicle and which enhance your vehicle ownership. All personal information is maintained securely and from time to time may be supplied to third party agencies to ensure that we can serve your needs.

TOIS365777

GST #R8987 66 779



0201IT0IS365777

ALL ITEMS ARE SUBJECT TO G.S.T.

OUT

INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ _____ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS, & ACCESSORIES DESCRIBED IN THIS WORK ORDER.

DATE _____ SIGNATURE _____

CUSTOMER NO. 10	ADVISOR ALANA HIEBERT	40293	TAG NO. 4822	INVOICE DATE 12/15/20	INVOICE NO. TOIS365777
CROWN TOYOTA 680-1717 WAVERLEY STREET WINNIPEG, MB R3T 6A9	LABOUR RATE 139.95	LICENSE NO. HYZ996	KILOMETERS 28,318	COLOUR BLACK/	STOCK NO. 94822
	YEAR/MAKE/MODEL 18/TOYOTA/COROLLA/SE 4DR PWLM SR AC			DELIVERY DATE 05/08/18	DELIVERY KMS. 28,318
VEHICLE I.D. NO. 2 T 1 B U R H E 1 J C 0 9 6 1 3 3		SELLING DEALER NO. 34027		IN SERVICE DATE 04/12/18	
F.T.E. NO.		P.O. NO.		R.O. DATE 12/15/20	05/08/18
RESIDENCE PHONE	BUSINESS PHONE 204-269-1572	COMMENTS E# ZRE172L-DEXSKK		MO: 28321	

TOTAL - MISC		51.12
COMMENTS-----		
94822		
TOTALS-----		
CONTROL#	ACCOUNT NUMBER	AMOUNT..
94822	1390	1216.94
TOTAL LABOR....		852.62
TOTAL PARTS....		313.20
TOTAL SUBLET...		0.00
TOTAL G.O.G....		0.00
TOTAL MISC.CHG.		51.12
TOTAL MISC.DISC		0.00
TOTAL TAX.....		0.00
TOTAL INVOICE \$		1216.94

THANK YOU

We are striving
to keep you
Completely Satisfied.
You may soon receive
a Service Survey.

- | | |
|--|--|
| | Outstanding |
| 1. Was appointment available when requested? | 9 10 |
| 2. Time waiting to speak to someone | <input type="radio"/> <input checked="" type="radio"/> |
| 3. Vehicle fixed right the first time | <input type="radio"/> <input checked="" type="radio"/> |
| 4. Service completed as promised | <input type="radio"/> <input checked="" type="radio"/> |
| 5. Service quality | <input type="radio"/> <input checked="" type="radio"/> |
| 6. Customer appreciation | <input type="radio"/> <input checked="" type="radio"/> |

If you cannot answer "Outstanding" (90% - 100%) please contact our Service Manager at (204) 275-4422. Below 90% reflects insufficient customer care in our opinion.

PAYMENT METHOD

- MASTERCARD _____
 VISA _____
 DEBIT CARD _____
 CASH _____
 AMEX _____

Shop supplies' fees as shown on this invoice include necessary cleaners & degreasers, misc. clips, bolts, fasteners, connectors, lubricants, etc.

WARRANTY

Unless otherwise indicated, TOYOTA parts are warranted for 24 months or 40,000 kms, whichever comes first. Labour is covered if the part was installed by a TOYOTA dealer, TOYOTA parts, like batteries, mufflers, shock absorbers and struts, may have different coverage, shown on a label or other document provided to the customer.

Internet Service Appointment
www.CrownToyota.ca

ACCOUNTING COPY-I

[END OF INVOICE]

03:08pm